

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002048/UTY3N2**Date:** 05/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00140692102

Claimant Vehicle No : SLU983K **Insured Vehicle No :** SJX7784E

Date of Loss: 02/03/2022 Nature of Claim: TP Claim No: SNM22D201548/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU983K**

Make & Model: VOLKSWAGEN GOLF A7, 1.2 (A) Engine No: CJZ614362

Reg. Date: 29/06/2015 (Man. Year: 2015) Chassis No: WVVZZZAUZFW320105

Colour: White Odometer: 116319 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,019.57	0.00	5,019.57	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	700.00	900.00	56.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	6,619.57	700.00	5,919.57	89.43

INSPECTION

Date of Assignment: 04/03/2022

Date Inspected: 07/03/2022 Inspected At: Zoom Autowerks Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-53
Singapore 417808

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2022)
Parts:	144	VOLKSWAGEN GOLF A7 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU983K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR ASSY RH	Not Necessary	987.10 FL	*- FL
2	1		*FRONT DOOR RH	Repair	1,392.90 FL	*- FL
3	1		*FRONT DOOR OUTER HANDLE GARNISH RH	Not Necessary	195.80 FL	*- FL
4	1		*FRONT DOOR OUTER GLASS MOULDING RH	Not Necessary	255.60 FL	*- FL
5	1		*FRONT DOOR TOP HINGE RH	Not Necessary	128.60 FL	*- FL
6	1		*FRONT DOOR LOWER HINGE RH	Not Necessary	132.50 FL	*- FL
7	1		*FRONT DOOR INNER LOCK RH	Not Necessary	496.50 FL	*- FL
8	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	386.70 FL	*- FL
9	1		*FRONT DOOR INNER TRIMBOARD RH	Not Necessary	786.40 FL	*- FL
10	1		*SET FRONT DOOR INNER TRIMBOARD CLIPS RH	Not Necessary	60.00 FL	*- FL
11	1		*FRONT DOOR POWER WINDOW MOTOR/LINKAGE ASSY RH	Not Necessary	755.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,577.30	0.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	557.73	0.00

Total Parts (\$\$)	5,019.57	0.00
---------------------------	-----------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACE & CHECK UP WIRING	New	50.00	0.00
2	TO RUST PROOF AFFECTED AREAS	New	200.00	0.00
3	TO REMOVE & INSTALL FRONT DOOR COMPONENTS	New	150.00	0.00
4	PANEL BEATING	New	600.00	300.00
5	TO RE-SPRAY THE AFFECTED AREAS	New	600.00	400.00
Gross Labour Cost (\$)			1,600.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >