

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002055/APA3Q2**Date:** 07/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100432773
Claimant Vehicle No :	SJF6358D	Insured Vehicle No :	SJA5751J
Date of Loss:	04/03/2022	Nature of Claim:	TP
		Claim No:	2091785666SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF6358D	Engine No:	R16A13004661
Make & Model:	HONDA CIVIC, 1.6 L VTI (A)	Chassis No:	JHMFD46208S201600
Reg. Date:	05/06/2008 (Man. Year: 2008)	Odometer:	217934 km
Colour:	Blue		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	LEAO 6 mm	Rear Left Side:	LEAO 6 mm
Front Right Side:	LEAO 6 mm	Rear Right Side:	LEAO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,398.00	3,620.72	2,777.28	43.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,690.00	820.00	32.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,908.00	5,310.72	3,597.28	40.38
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	8,908.00	4,200.00	4,708.00	52.85
+ GST 7.00/7.00% (S\$)	623.56	294.00	329.56	52.85
Nett Amount (S\$)	9,531.56	4,494.00	5,037.56	52.85
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
Nett Liability (S\$)		5,334.00		

INSPECTION

Date of Assignment:	04/03/2022		
Date Inspected:	04/03/2022	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	883.20 FL	*698.00 FL
2	1		*H EMBLEM	Necessary	36.00 FL	*36.00 FL
3	2		*BOOTLID REFLECTORS	Cut	487.20 FL	*487.20 FL
4	1		*BOOTLID LOCK	Damaged	285.00 FL	*285.00 FL
5	1		*BOOTLID W/STRIP	Cut	243.00 FL	*243.00 FL
6	1		*1.6 EMBLEM	Necessary	42.10 FL	*42.10 FL
7	1		*I-VTEC EMBLEM	Necessary	48.10 FL	*48.10 FL
8	1		*CIVIC EMBLEM	Necessary	42.50 FL	*42.50 FL
9	1		*BOOTLID INSULATOR	Not Necessary	243.50 FL	*- FL
10	2		*TAILLAMP	Cracked	696.40 FL	*616.00 FL
11	1		*REAR BUMPER	Distorted	638.00 FL	*638.00 FL
12	2		*REAR BUMPER RETAINERS	Necessary	167.00 FL	*62.00 FL
13	2		*REAR BUMPER HOLDER	Not Necessary	140.00 FL	*- FL
14	8		*REAR BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
15	1		*END PANEL	Dented	733.20 FL	*325.00 FL
16	1		*END PANEL INNER GARNISH	Deformed	247.00 FL	*145.00 FL
17	1		*REAR FENDER INNER TRIM	N/S Torn	384.80 FL	*275.00 FL
18	1		*SPARE TYRE CARDBOARD	Deformed	297.00 FL	*297.00 FL
19	1		*EXHAUST PIPE CHROME	Not Necessary	160.00 FL	*- FL
20	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
21	1		*BOOTLID SPOILER	Not Necessary	1,500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,560.00	4,475.90
- List Item Discount on L Items 20.00/20.00% (S\$)	1,162.00	855.18
Total Parts (S\$)	6,398.00	3,620.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	30.00	30.00
4	RUST PROOFING	New	80.00	60.00
Gross Labour Cost (\$\$)			2,510.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >