

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578
 Defu Industrial Park C, Singapore 539188
 Tel : 6343-0934 Fax : 6343-0921
 Email : jmartauto@gmail.com
 Registration No: 201400246D
 GST Reg. No: 201400246D

KK Auto Consultants hence notify
 Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4-Mar-22

Our ref : TP/5097/22

Yip Kam Kit

TP ALG

Ceiling. JHMF17462085201600

RE : estimate cost for vehicle no : SJF 6358D

1 pc	bootlid <i>Dented</i>	\$	883.20	698.
1 pc	H emblem <i>new</i>		36.00	—
2 pcs	bootlid reflectors <i>cut</i>		487.20	—
1 pc	bootlid lock <i>new</i>		285.00	—
1 pc	bootlid w/strip <i>cut</i>		243.00	—
1 pc	1.6 emblem		42.10	—
1 pc	I-VTEC emblem <i>new</i>		48.10	—
1 pc	Civic emblem		42.50	—
1 pc	bootlid insulator <i>new</i>		243.50	x.
2 pcs	taillamp <i>new</i>		696.40	616.
1 pc	rear bumper <i>Dishled</i>		638.00	—
2 pcs	rear bumper retainers <i>new</i>		167.00	62.
2 pcs	rear bumper holder <i>new</i>		140.00	—
8 pcs	rear bumper clips <i>new</i>		36.00	—
1 pc	end panel <i>Dented</i>		733.20	325.
1 pc	end panel inner garnish <i>new</i>		247.00	145
2 pcs	rear fender inner trim <i>LH Torn</i>		584.80	275.
1 pc	spare tyre cardboard <i>new</i>		297.00	—
1 pc	exhaust pipe chrome <i>new</i>		160.00	—
			5,810.00	
			1,162.00	
			4,648.00	
			250.00	snett
1 pc	reverse sensor <i>new</i>		1,500.00	x.
1 pc	bootlid spoiler <i>new</i>		1,200.00	800
			1,200.00	800
			30.00	—
			80.00	60
			8,908.00	
			623.56	
			9,531.56	

less 20%

Plus 7% GST

SD : Nine thousand five hundred thirty-one & cents fifty-six only.

Adrian L
 1/5 04/03/22
 068495
 Total: 5310.72
 L/S: 4.2K