

Case Details

Case Reference Number :

TAX/03/22/2011

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB1322J

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-17639-ID

Assigned By : Taxi Claims Manager

Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 03/03/2022 03:15 AM

Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			LATCH ASM-RR S/D -L	1	139.98	139.98	10.00	125.98	Replace	0	0	Not Give	✓ Xun
One Time Key In	Main			LATCH ASM-FRT S/D -L	1	156.84	156.84	10.00	141.16	Replace	0	0	Not Give	✓ Xun
One Time Key In	Main			MOTOR ASM-RR S/D WDO REG -L	1	169.00	169.00	10.00	152.10	Replace	0	0	Check	✓ Xun
One Time Key In	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ ne
One Time Key In	Main			HINGE ASM-RR S/D UPR-L	1	46.90	46.90	10.00	42.21	Replace	0	0	Check	✓ Xun
One Time Key In	Main			HINGE ASM-RR S/D LWR-L	1	47.22	47.22	10.00	42.50	Replace	0	0	Check	✓ Xun
One Time Key In	Main			MOTOR ASM-FRT S/D WDO REG-L	1	169.00	169.00	10.00	152.10	Replace	0	0	Not Give	✓ Xun
One Time Key In	Main			REGULATOR ASM-FRT S/D WDO-L	1	324.06	324.06	10.00	291.65	Replace	0	0	Not Give	✓ Xun
One Time Key In	Main			PANEL-BODY SI OTR-L	1	1,747.82	1,747.82	10.00	1,573.04	Replace	1	0	Repair	✓ Ry

Total Spare Part Cost 8,346.48

Lump Sum Discount (%) 0.00

Final Spare Part Cost 8,346.48

Surveyor Total 2,048.14

Lump Sum Dis (%) 0

Final Sur Total 2,048.14

SMRT Recommendation											Surveyor Approval			
OM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR ASM-RR SI-L	1	2,185.04	2,185.04	10.00	1,966.54	Replace	1	1,966.54	Replace	bt
One Time Key In	Main			DOOR ASM-FRT SI-L	1	2,338.76	2,338.76	10.00	2,104.88	Replace	1	0	Repair	Ry
One Time Key In	Main			REGULATOR ASM-RR S/D WDO-L	1	265.30	265.30	10.00	238.77	Replace	0	0	Not Give	Xun
One Time Key In	Main			STICKER ELECTRIC (LOGO)	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	nee
One Time Key In	Main			WHEEL	1	618.07	618.07	10.00	556.26	Replace	1	0	Repair	Ry
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	Xun
One Time Key In	Main			FASCIA-RR BPR	1	758.47	758.47	10.00	682.62	Replace	1	0	Repair	Ry
One Time Key In	Main			BRACKET-RR BPR FASCIA SI MTG	1	46.07	46.07	10.00	41.46	Replace	0	0	Not Give	Xun
One Time Key In	Main			BRACKET ASM-RR BPR FASCIA SI-L	1	29.85	29.85	10.00	26.87	Replace	0	0	Not Give	Xun
Total Spare Part Cost									8,346.48	Surveyor Total 2,048.14 ✓				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									8,346.48	Final Sur Total 2,048.14				

2084.14

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	3,600.00	800	
Total:			3,600.00	800.00 ✓	

800

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR LH	428.00	220 ✓	
2	Main	TO RESPRAY REAR DOOR LH	428.00	220 ✓	
Total:			1,942.00	940.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY REAR FENDER LH	428.00	220 ✓	
4	Main	TO RESPRAY REAR BUMPER	428.00	220 ✓	
5	Main	TO RESPRAY RIM	230.00	60 ✓	
Total:			1,942.00	940.00 ✓	

940.

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	80 ✓	
2	Main	TO TRANSFER DOOR MECHANISM	240.00	60 ✓	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30 ✓	
4	Main	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0	Xnn
5	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150 ✓	
6	Main	ISOLATED OF (EV) (NET)	150.00	150.00 ✓	
7	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	Xnn
8	Main	TO REPLACE SUNDRY PARTS	100.00	0	Xnn
9	Main	TO WASH AND VACUUM	60.00	0	Xnn.
Total:			1,320.00	470.00	

470

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,346.48	2,048.14
Total Labour Cost	3,600.00	800.00
Total Spray Painting	1,942.00	940.00
Other	1,320.00	470.00
Overall Total	15,208.48	4,258.14
Lump Sum Repair Option		☐
Lump Sum Total	0.00	4,258.14

4,258.14

#

6 days

13:Ub

https://vacsweb.smrt.com.sg/Estimation.aspx

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Approved Amount

4,258.14

No of Repair Days*

8

6

Remarks

PART BY PART REPAIR / BEFORE PAINT PHOTO / NEW
PART AND OLD DAMAGE PART PHOTO.

Surveyor Name

Taufikh

Signature



Save

Clear

Survey Date

04/03/2022

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufikh 974125749

06 days

WP' 4/3/22 @ 1230pm

P/P Resurvey before paint

Taufikh @ WhatsApp