

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0157/2022/JT
DATE : 3-Mar-22
WIP : 14354

*Veron.**07 Days. H.S.
\$16095.24.*VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/3/22**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS YEO YU LING, ASHTON VIRGINA
ADDRESS : BLK 136 BISHAN ST 12
#02-424
SINGAPORE 570136
TELEPHONE : HP +65 97904223
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800029999-03
VEHICLE NO : **SLX 5189 M**
MODEL CODE : AUDI A3 SB 1.0 TFSI
MODEL YEAR : 28/3/2018
ENGINE NO : CHZ 424850
CHASSIS NO : WAUZZZ8V3JA088987
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Mar-22
PLACE OF ACCIDENT : 42 MACTAGGART ROAD PARKED ALONG THE
SIDE OF THE ROAD, IN PARKING LOT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 5189 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X-
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X.
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00 280.00	✓
4	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	X.
5	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N \$ 3,200.00	X
SUB TOTAL LABOUR CHARGES		: \$ <u>6,060.00</u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 5189 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RENEW FRONT WINDSCRREN.	S/N \$	480.00	✓
7	TO INSTALL SOLAR FILM FOR FRONT WINDSCRREN.	S/N \$	400.00	✓
8	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$	200.00	✓
9	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.	S/N \$	800.00	? ✓
10	TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	? ✓
SUB TOTAL LABOUR CHARGES		:	\$ 4,280.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 5189 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
11	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY SUBFRAME.	S/N \$ 2,400.00	? ✓ <i>86/8</i>
12	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR. CUT OUT AND REWELD RHS LOWER A-PILLAR AND RHS SILL PANEL. TO REPAIR RHS UPPER A-PILLAR AND BONNET. REINSTALL ALL PARTS REMOVED.	\$ 6,300.00	2000 ✓
13	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS A-PILLAR, RHS SILL PANEL, ROOF CHANNEL AND DOOR ENTRANCES. TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT.	\$ 6,500.00	2200 ✓
14	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	240.500
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	182. ✓
TOTAL LABOUR CHARGES		: \$ 26,444.00	

Car in -

2/3/22

wp: 14354

Kiam/chox 0000

AIG-Adrian

- 7 days

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 5189 M

			DAMAGED PARTS & PRICE		REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
1	FRONT FENDER - RH <i>distorted</i>	1 S	954.00	✓	763.20
2	POP RIVET <i>new</i>	8 S	31.00	✓	24.32
3	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1 S	75.00	✓	
4	FRONT FENDER BRACKET - RH <i>Best</i>	1 S	56.00	✓	88/s 44.40
5	FRONT FENDER CLOSING ELEMENT - RH LOWER <i>2 new</i>	1 S	68.00	✓	
6	FRONT FENDER BRACE - RH <i>Not new</i>	1 S	107.00	✓	
7	FRONT FENDER BRACKET END - RH <i>Best</i>	1 S	31.00	✓	24.24
8	FRONT FENDER INSULATION - RH <i>delid.</i>	1 S	39.76	✓	88/s
9	FRONT FENDER CLOSING ELEMENT - RH <i>Best</i>	1 S	29.12	✓	
10	SPREADER RIVET <i>new</i>	2 S	4.00	✓	2.88
11	FRONT WHEEL HOUSING LINER - RH <i>new</i>	1 S	182.00	✓	146.40
12	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1 S	60.00	✓	
13	FRONT BUMPER <i>new</i>	1 S	2,146.00	✓	
14	FRONT BUMPER GUIDE SECTION - RH <i>Not new</i>	1 S	43.00	✓	
15	HEADLIGHT - RH <i>new</i>	1 S	5,455.00	✓	
16	FRONT DOOR - RH <i>distorted</i>	1 S	2,973.00	✓	2378.40
17	FRONT DOOR OUTER SEAL - RH <i>new</i>	1 S	179.00	✓	142.80
18	BONDING AGENT <i>new</i>	1 S	51.00	✓	
19	CLEANING SOLUTION <i>new</i>	1 S	74.00	✓	
20	APPLICATOR <i>new</i>	1 S	8.00	✓	
SUB TOTAL SPARE PARTS			\$	12,583.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6366 1103

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 5189 M

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT DOOR ATTACHMENT PARTS <i>Ne m</i>	1	\$	252.00	+
22	FRONT DOOR CATCH - RH <i>Ne m</i>	1	\$	105.00	? X
23	FRONT DOOR SEAL INNER - RH <i>Ne m</i>	1	\$	179.00	+
24	FRONT DOOR HINGE UPPER - RH UPPER / LOWER <i>Ne m</i>	2	\$	91.00	? X
25	FRONT DOOR HINGE LOWER - RH UPPER / LOWER <i>Best</i>	2	\$	89.00	✓ 36
26	FRONT PRESSURE DATA PLATE <i>Ne m</i>	1	\$	34.00	✓ 36.96
27	DATA TAG <i>Ne m</i>	1	\$	515.00	+
28	FRONT DOOR WIRING SET <i>Ne m</i>	1	\$	642.00	+
29	WING MIRROR MOUNTING - RH <i>Ne m</i>	1	\$	1,130.00	+
30	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH <i>Ne m</i>	1	\$	302.00	? X
31	ROOF MOLDING - RH <i>Ne m</i>	1	\$	665.00	+
32	WINDSCREEN WATER DEFLECTOR STRIP - RH <i>Ne m</i>	1	\$	75.00	+
33	FRONT DOOR WINDOW GUIDE - RH <i>Ne m</i>	1	\$	467.00	+
34	A-PILLAR - RH <i>Best</i>	1	\$	3,734.00	+
35	FRONT STONE CHIP GUARD - RH <i>Ne m</i>	1	\$	82.00	✓ 64.88
36	FRONT ADHESIVE TAPE <i>Ne m</i>	1	\$	59.00	? X
37	FRONT ALUMINIUM RIM <i>Best</i>	1	\$	1,303.00	✓ 1042.40
38	RUBBER VALVE <i>Ne m</i>	4	\$	15.00	✓ 592
39	TRACK CONTROL ARM <i>Best</i>	1	\$	393.00	? 314
40	STABILIZER <i>Ne m</i>	1	\$	451.00	? X
SUB TOTAL SPARE PARTS		:	\$	10,583.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1163

EMAIL: NORA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 5189 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	FRONT WHEEL BEARING HOUSING <i>Dmgd</i>	1	\$ 627.00	✓	501.20
42	FRONT WHEEL HUB BEARING <i>Dmgd</i>	1	\$ 553.00	✓	442
43	FRONT WHEEL BEARING HOUSING GUIDE JOINT - RH <i>myd</i>	1	\$ 134.00	✓	107.20
44	COUPLING ROD <i>Not nee</i>	1	\$ 105.00	✓ X	
45	DRIVE SHAFT - RH <i>Not nee</i>	1	\$ 1,517.00	X	
46	GAS SHOCK ABSORBER <i>Not nee</i>	1	\$ 281.00	✓ X	
47	TRACK ROD <i>Not nee</i>	1	\$ 98.00	✓	78.40
48	TIE ROD END - RH <i>Dmgd</i>	1	\$ 126.00	✓	100.40
49	STEERING GEAR <i>Not nee</i>	1	\$ 5,538.00	X	
50	ASSEMBLY REINFORCEMENT <i>Not nee</i>	1	\$ 1,105.00	✓ X	
51	RUBBER BUSHES SET <i>Not nee</i>	1	\$ 116.00	✓ X	
52	FRONT DOOR CORNER TRIM - RH <i>Not nee</i>	1	\$ 51.00	X	
53	PLENUM CHAMBER <i>Not nee</i>	1	\$ 199.00	X	
54	FRONT WINDSCREEN <i>Not nee</i>	1	\$ 1,206.00	X	
55	RAIN SENSOR GEL FOIL <i>Not nee</i>	1	\$ 130.00	X	
56	SPRING CLIP <i>Not nee</i>	1	\$ 23.00	X	
57	ARYLIC SEALANT <i>Not nee</i>	S/N	\$ 180.00	X	
58	CAVITY WAX <i>Not nee</i>	S/N	\$ 140.00	X	
59	STONE CHIP <i>Not nee</i>	S/N	\$ 180.00	X	
60	METAL FILLER POWDER <i>Not nee</i>	S/N	\$ 280.00	X	
61	FRONT WINDSCREEN SEALANT <i>Not nee</i>	S/N	\$ 200.00	X	
62	RHS FRONT TYRE <i>Not nee</i>	S/N	TBC	X	
63	SUNDRIES <i>Not nee</i>	\$	600.00		155.20

TOTAL SPARE PARTS	:	\$	36,555.00
TOTAL LABOUR CHARGES	:	\$	26,444.00
GRAND TOTAL	:	\$	62,999.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0157/2022/JT
14-Mar-22
CHANG
1 of 1
SLX 5189 M
AUDI A3 SB 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO CUT OUT AND WELD RHS A-PILLAR BRACKET.	\$ 1,400.00	500 ✓
2	TO RESPRAY RHS A-PILLAR BRACKET.	\$ 700	275 ✓
Parts			
1	REPAIR SET FOR STEERING GEAR BOX <i>New</i>	\$ 50.00	✓ 39.92
2	A-PILLAR BRACKET - RH <i>cut</i>	\$ 72.00	✓ 57.20
3	FRONT FENDER TOP COVER - RH <i>rehd</i>	\$ 46.00	✓ 36.24
4	FRONT DOOR WIRING CONNECTOR <i>cruld</i>	\$ 42.00	✓ 33.36
5	FRONT DOOR FOAM - RH <i>torn</i>	\$ 14.00	✓ 11.04
GRAND TOTAL		\$ 1,694.00	

For Premium Automobiles Pte Ltd

Adrian Li
H.S.
17/03/22



Authorised Signature

To add 1 more repair day for
the replacement of the A-Pillar
Bracket.

H.S.

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-2

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0157/2022/JT
15-Mar-22
CHANG
1 of 1
SLX 5189 M
AUDI A3 SB 1.0 TFSI

Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO REMOVE AND RENEW LHS REAR RIM.	S/N	\$ 40.00	✓
<u>Parts</u>				
1	ALUMINIUM RIM - LH REAR	1	\$ 1,303.00	✓ 1042 40
GRAND TOTAL			\$ 1,343.00	

For Premium Automobiles Pte Ltd

Adrian Ling
15/03/22
H.S.

Authorised Signature

