

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0157/2022/JT
DATE : 3-Mar-22
WIP : 14354

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS YEO YU LING, ASHTON VIRGINA
ADDRESS : BLK 136 BISHAN ST 12
#02-424
SINGAPORE 570136
TELEPHONE : HP +65 97904223
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800029999-03
VEHICLE NO : **SLX 5189 M**
MODEL CODE : AUDI A3 SB 1.0 TFSI
MODEL YEAR : 28/3/2018
ENGINE NO : CHZ 424850
CHASSIS NO : WAUZZZ8V3JA088987
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Mar-22
PLACE OF ACCIDENT : 42 MACTAGGART ROAD PARKED ALONG THE
SIDE OF THE ROAD, IN PARKING LOT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 5189 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. S/N \$	360.00	X-
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$	350.00	X-
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. S/N \$	350.00 280	
4	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. S/N \$	1,800.00	X-
5	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES. S/N \$	3,200.00	X-
SUB TOTAL LABOUR CHARGES		: \$ 6,060.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 5189 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RENEW FRONT WINDSCRREN.	S/N \$	480.00	✓
7	TO INSTALL SOLAR FILM FOR FRONT WINDSCRREN.	S/N \$	400.00	✓
8	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$	200.00	✓
9	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.	S/N \$	800.00	?
10	TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	?
SUB TOTAL LABOUR CHARGES		:	\$	<u>4,280.00</u>

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 5189 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
11	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY SUBFRAME.	S/N \$ 2,400.00	?
12	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR. CUT OUT AND REWELD RHS LOWER A-PILLAR AND RHS SILL PANEL. TO REPAIR RHS UPPER A-PILLAR AND BONNET. REINSTALL ALL PARTS REMOVED.	\$ 6,300.00	2000
13	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS A-PILLAR, RHS SILL PANEL, ROOF CHANNEL AND DOOR ENTRANCES. TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT.	\$ 6,500.00	2200
14	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	240
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	182.
TOTAL LABOUR CHARGES		: \$ 26,444.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 5189 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - RH <i>Distorted</i>	1	\$ 954.00	✓
2	POP RIVET <i>new</i>	8	\$ 31.00	✓
3	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 75.00	+
4	FRONT FENDER BRACKET - RH ?	1	\$ 56.00	?
5	FRONT FENDER CLOSING ELEMENT - RH LOWER ?	1	\$ 68.00	?
6	FRONT FENDER BRACE - RH ?	1	\$ 107.00	?
7	FRONT FENDER BRACKET END - RH ?	1	\$ 31.00	?
8	FRONT FENDER INSULATION - RH ?	1	\$ 48.00	?
9	FRONT FENDER CLOSING ELEMENT - RH ?	1	\$ 37.00	?
10	SPREADER RIVET ?	2	\$ 4.00	?
11	FRONT WHEEL HOUSING LINER - RH <i>for</i>	1	\$ 183.00	✓
12	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 60.00	+
13	FRONT BUMPER <i>new</i>	1	\$ 2,146.00	+
14	FRONT BUMPER GUIDE SECTION - RH <i>not an</i>	1	\$ 43.00	+
15	HEADLIGHT - RH <i>new</i>	1	\$ 5,455.00	+
16	FRONT DOOR - RH <i>Distorted</i>	1	\$ 2,973.00	✓
17	FRONT DOOR OUTER SEAL - RH <i>new</i>	1	\$ 179.00	✓
18	BONDING AGENT ?	1	\$ 51.00	?
19	CLEANING SOLUTION ?	1	\$ 74.00	?
20	APPLICATOR ?	1	\$ 8.00	?
SUB TOTAL SPARE PARTS		:	\$ 12,583.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 5189 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 252.00	+
22	FRONT DOOR CATCH - RH ?	1	\$ 105.00	?
23	FRONT DOOR SEAL INNER - RH <i>new</i>	1	\$ 179.00	+
24	FRONT DOOR HINGE UPPER - RH UPPER / LOWER ?	2	\$ 91.00	?
25	FRONT DOOR HINGE LOWER - RH UPPER / LOWER ?	2	\$ 89.00	?
26	TYRE PRESSURE DATA PLATE <i>new</i>	1	\$ 34.00	✓
27	DATA TAG <i>new</i> ?	1	\$ 515.00	+
28	FRONT DOOR WIRING SET <i>new</i>	1	\$ 642.00	+
29	WING MIRROR MOUNTING - RH <i>new</i>	1	\$ 1,130.00	+
30	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH ?	1	\$ 302.00	?
31	ROOF MOLDING - RH <i>new</i>	1	\$ 665.00	+
32	WINDSCREEN WATER DEFLECTOR STRIP - RH <i>new</i>	1	\$ 75.00	+
33	FRONT DOOR WINDOW GUIDE - RH <i>new</i>	1	\$ 467.00	+
34	A-PILLAR - RH <i>Repis</i>	1	\$ 3,734.00	+
35	FRONT STONE CHIP GUARD - RH <i>new</i>	1	\$ 82.00	✓
36	FRONT ADHESIVE TAPE ?	1	\$ 59.00	?
37	FRONT ALUMINIUM RIM <i>new</i>	1	\$ 1,303.00	✓
38	RUBBER VALVE <i>new</i>	4	\$ 15.00	+
39	TRACK CONTROL ARM ?	1	\$ 393.00	?
40	STABILIZER ?	1	\$ 451.00	?
SUB TOTAL SPARE PARTS		:	\$ 10,583.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 5189 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	FRONT WHEEL BEARING HOUSING ?	1	\$ 627.00	?	
42	FRONT WHEELHUB BEARING ?	1	\$ 553.00	?	
43	FRONT WHEEL BEARING HOUSING GUIDE JOINT - RH ?	1	\$ 134.00	?	
44	COUPLING ROD ?	1	\$ 105.00	?	
45	DRIVE SHAFT - RH <i>new</i>	1	\$ 1,517.00	x	
46	GAS SHOCK ABSORBER ?	1	\$ 281.00	?	
47	TRACK ROD ?	1	\$ 98.00	?	
48	TIE ROD END - RH ?	1	\$ 126.00	?	
49	STEERING GEAR <i>new</i>	1	\$ 5,538.00	x	
50	ASSEMBLY REINFORCEMENT ?	1	\$ 1,105.00	?	
51	RUBBER BUSHES SET ?	1	\$ 116.00	?	
52	FRONT DOOR CORNER TRIM - RH <i>new</i>	1	\$ 51.00	x	
53	PLENUM CHAMBER <i>new</i>	1	\$ 199.00	x	
54	FRONT WINDSCREEN <i>new</i>	1	\$ 1,206.00	+	
55	RAIN SENSOR GEL FOIL <i>new</i>	1	\$ 130.00	x	
56	SPRING CLIP <i>new</i>	1	\$ 23.00	x	
57	ARYLIC SEALANT <i>new</i>	S/N	\$ 180.00	x	
58	CAVITY WAX <i>new</i>	S/N	\$ 140.00	x	
59	STONE CHIP <i>new</i>	S/N	\$ 180.00	x	
60	METAL FILLER POWDER <i>new</i>	S/N	\$ 280.00	x	
61	FRONT WINDSCREEN SEALANT <i>new</i>	S/N	\$ 200.00	x	
62	RHS FRONT TYRE <i>new</i>	S/N	TBC	x	
63	SUNDRIES		\$ 600.00		
TOTAL SPARE PARTS		:	\$ 36,555.00		
TOTAL LABOUR CHARGES		:	\$ 26,444.00		
GRAND TOTAL		:	\$ 62,999.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *04/03/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 07 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT