

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 2022 22004114FR Date: 16th Nov 2022

Our Ref: CS6/AIS22002063/Gny3e2

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SML 5183E ACCIDENT ON 02/03/2022

We thank you for your instruction on 07/03/2022.

The following vehicle information was recorded:

Registration Number : SML 5183E

Make & Model : Toyota Vios 1.5 E (Auto) Chassis Number : MR2B23F3201174483

Year of Registration : 2019 Engine Capacity : 1496 cc

- 1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about <u>7 (Seven)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.