

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

JHMGF88509S202401

ESTIMATE OF REPAIR

Veh# SMG5451H

TP III
Aches.

Model:

HONDA JAZZ

13/10/2010

Accident Date : 4/3/2022

Location : BLK 265A COMPASSVALE STREET

3P:

SKQ9051Z (III)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>rehd</i>	670.8	485.	
2	10 pcs	Front bumper clips <i>new</i>		30.00	✓
3	1 pc	Front bumper o/s retainer <i>new</i>	120.6	85.	
4	1 pc	Front o/s head-lamp <i>crackd</i>	1466.4	748	
5	1 pc	Front o/s fog-lamp <i>new</i>	138.80	+	
6	1 pc	Front o/s fog-lamp garnish <i>at</i>	94.40	✓	
7	1 pc	Front o/s fender <i>crackd</i>	432.30	✓	
8	1 pc	Front o/s fender inner trim <i>new</i>	211.40	+	
9	1 pc	Front o/s fender panel <i>new</i>	443.50	+	
10	1 pc	Front o/s rim <i>at</i>		600.00	400.
11	1 pc	Rear o/s kunckle <i>new</i>	310.00	+	
12	1 pc	Front o/s bearing <i>new</i>	135.40	+	
		Wiper washer Tank <i>rehd</i>	85		
		Sub-Total:	4,023.40	630.00	0.00
			20%	0%	0%
		After Less %:	3,218.72	630.00	0.00
		Labour			
1		To dismantle, straighten and welding front damage parts	1,000.00	500	
2		To spray painting.	700.00	400	
3		To remove and refit front under carriage	100.00	+	
4		To check wiring.	80.00	30	
5		To re-seal anti-rust.	50.00	+	
		Sub-Total:	1,930.00		
		Total:	5,778.72		
		After Less 20%:	4,622.98		

Chan

Chan San Choon
Director
DipEng. AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SMG5451H ESTIMATEPg1

Total: 2878.16
L/S: 2.3K.
04 Days.

Mobil 1



PAYNOW