



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: WINNIE			Ref: CC4/ASM22002068/Bea3q2 Date: 08/08/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SLP 4495C	Veh. Inspected	SNB 8629H
	Policy No.	GA214185	Coverage (\$)	0.00
	Claim No.	S2M03UYC	Excess (\$)	0.00
	Assign From		Assign Date	07/03/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA YARIS CROSS	c.c	1490
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MXPB102010973	Colour	GOLD
	Odometer	5823 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/65 R16	DUNLOP	6 mm
	L/H Front Tyre	205/65 R16	DUNLOP	6 mm
	R/H Rear Tyre	205/65 R16	DUNLOP	6 mm
	L/H Rear Tyre	205/65 R16	DUNLOP	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/03/2022	Inspection Date	08/03/2022
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>8 Working Days</b>