



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : GBH4717Z

Date of Accident : 03 March 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Hi Power Pte Ltd

Date : 04 March 2022

Estimate To Repair SJK5879Y - Toyota Altis

Chassis No : MR053ZEE106121769

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	rear bumper	\$ 486.50
02	10 pcs	rear bumper clips @ \$4.30	\$ 43.00
03	2 pcs	rear bumper side retainer @ \$70.40	\$ 140.80
04	1 pc	rear bumper reflexor o/s	\$ 58.00
05	1 pc	rear boot lid	\$ 775.00
06	1 pc	rear boot lid lamp o/s	\$ 355.00
07	1 pc	rear boot lid outer chrome moulding	\$ 233.80
08	1 pc	rear boot lid weather strip	\$ 185.00
09	1 pc	rear boot lid toyota logo	\$ 58.60
10	1 pc	rear boot lid 1.6 logo	\$ 46.60
11	1 pc	rear boot lid corolla logo	\$ 61.00
12	1 pc	rear boot lid altis logo	\$ 48.00
13	1 pc	rear boot lid LX logo	\$ 48.00
14	1 pc	rear end panel	\$ 590.60
15	1 pc	rear end panel inner trim	\$ 202.70
Less 25 %			\$ 3,332.60
			\$ 833.15
			\$ 2,499.45
LABOUR & MISC. CHARGES			
01		Putty and spray painting rear of the affected portion.	\$ 700.00
02		Panel beating, knocking and straighten rear of the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 700.00
03		To check electrical lighting concerned.	\$ 70.00
04		To reinstall of rear bumper parking sensor.	\$ 60.00
05		To rust-proofing of the affected areas.	\$ 120.00
06		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 100.00
16	1 pc	rear tail lamp o/s	\$ 460.00
Total			\$ 2,210.00
			\$ 4,709.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 881.7
252
P- 661.27
S.N- 200
L- 1020



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : GBH4717Z

Date of Accident : 03 March 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Hi Power Pte Ltd

Date : 10 March 2022

Supplementary To Repair SJK5879Y - Toyota Altis

Chassis No : MR053ZEE106121769

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	2 pcs	rear bumper side retainer @ \$70.40 <i>Repair</i>	\$ 140.80 <i>X</i>
02	1 pc	rear end panel <i>Repair</i>	\$ 590.60 <i>X</i>
03	1 pc	rear end panel inner trim <i>Repair</i>	\$ 202.70 <i>X</i>
04	1 pc	rear bumper sponge with bar <i>Don</i> <i>284.20</i>	\$ 395.00
05	1 pc	o/s end panel bracket <i>ID</i>	\$ 68.00 <i>///</i>
			\$ 1,397.10
Less 25 %			\$ 349.28
			\$ 1,047.83
Total			\$ 1,047.83