

AlGAsia Insured's Veh No : SJX8299H
Date of Accident : 05 March 2022



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Au Chee Keong

Date : 07 March 2022

Estimate To Repair SNE2168U - B.M.W 216D Active Tourer D/AB LED
Chassis No : WBA2B32070V926039

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper <i>De/to. n</i>	\$ 854.50
02	1 pc	front bumper base n/s <i>ns</i>	\$ 79.10 <i>X</i>
03	1 pc	front bumper fog lamp n/s <i>17</i>	\$ 276.40 <i>X</i>
04	1 pc	front bumper fog lamp trim n/s <i>ground</i>	\$ 82.50 <i>→</i>
05	1 pc	front bumper fog lamp chrome moulding n/s <i>sent</i>	\$ 95.00 <i>→</i>
06	2 ps	front bumper parking sensor @ \$280.00 <i>n/s shared 225</i>	\$ 560.00 <i>12C</i>
07	6 ps	front bumper parking sensor holder @ \$85.00 <i>17</i>	\$ 510.00 <i>X</i>
08	1 pc	front bumper side retainer n/s <i>cm</i>	\$ 19.00 <i>→</i>
09	1 pc	headlamp n/s <i>ene</i>	\$ 2,348.50 <i>→</i>
10	1 pc	headlamp bracket n/s <i>ns</i>	\$ 145.90 <i>X</i>
11	1 pc	n/s front fender <i>sent/marred.</i>	\$ 596.70 <i>→</i>
12	1 pc	n/s front fender inner cowling <i>17</i>	\$ 145.60 <i>4</i>
13	6 ps	n/s front fender inner cowling clips @ \$5.00 <i>17</i>	\$ 30.00 <i>X</i>
Less 10 %			\$ 5,743.20
			\$ 574.32
			\$ 5,168.88
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 80.00 <i>20</i>
02		To reinstall of rear bumper parking sensor.	\$ 120.00 <i>50</i>
03		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ 450.00 <i>60</i>
04		To check steering geometry and computer wheel alignment.	\$ 80.00 <i>17 X</i>
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00 <i>300</i>
06		Putty and spray painting of the affected portion.	\$ 800.00 <i>400</i>
			\$ 2,280.00
Total			\$ 7,448.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2- 4221-20
102
3799.08
830
4628.08
208
3703