

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 04.03.22

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLK2942T**
MODEL : **HONDA SHUTTLE**
DATE OF ACCIDENT : 03.03.22
TIME OF ACCIDENT : 18:20HRS

Asher. GK81206902

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 1,600.00	\$ 1,600.00
2	REAR BUMPER EXHAUST COVER GARNISH <i>M</i>	1	\$ 57.00	\$ 57.00
3	REAR BUMPER REFLECTOR <i>2nd</i>	2	\$ 49.00	\$ 98.00
4	REAR BUMPER REFLECTOR GARNISH <i>M</i>	2	\$ 68.00	\$ 136.00
5	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 19.00	\$ 19.00
6	REAR BUMPER TOWING BRACKET <i>new</i>	1	\$ 294.00	\$ 294.00
7	REAR BUMPER SIDE INNER BRACKET <i>new</i>	2	\$ 39.00	\$ 78.00
8	REAR BUMPER SPONGE <i>crushd</i>	2	\$ 47.00	\$ 94.00
9	REAR BUMPER SIDE RETAINER <i>m</i>	2	\$ 32.00	\$ 64.00
10	TAIL GATE <i>Distohd</i>	1	\$ 1,900.00	\$ 1,900.00
11	TAIL GATE OUTER GARNISH C/W MOULDING (CHROME) <i>new</i>	1	\$ 695.00	\$ 695.00
12	TAIL GATE NUMBER PLATE LAMP <i>new</i>	2	\$ 38.00	\$ 76.00
13	TAIL GATE LOGO <i>new</i>	1	\$ 45.00	\$ 45.00
14	TAIL GATE EMBLEM " SHUTTLE" <i>new</i>	1	\$ 70.00	\$ 70.00
15	TAIL GATE LAMP <i>lit</i>	2	\$ 395.00	\$ 790.00
16	TAIL GATE DAMPER <i>new</i>	2	\$ 125.00	\$ 250.00
17	TAIL GATE HINGE <i>new</i>	2	\$ 50.00	\$ 100.00
18	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 40.00	\$ 40.00
19	TAIL GATE STOPPER <i>new</i>	2	\$ 25.00	\$ 50.00
20	TAIL GATE INNER LOCK <i>Dehd</i>	1	\$ 190.00	\$ 190.00
21	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 24.00	\$ 24.00
22	TAIL GATE WEATHER STRIP <i>lit</i>	1	\$ 190.00	\$ 190.00
23	TAIL GATE DETECTOR <i>new</i>	1	\$ 296.00	\$ 296.00
24	TAIL GATE DETECTOR WIRE HARNESS <i>new</i>	1	\$ 586.00	\$ 586.00
25	TAIL GATE INNER TRIM <i>crushd</i>	1	\$ 320.00	\$ 320.00
26	TAILGATE REVERSE CAMERA <i>new</i>	1	\$ 1,150.60	\$ 1,150.60
27	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 160.00	\$ 160.00

1150 985

1192

TO : **AIG MOTOR CLAIMS DEPTS**
 VEHICLE NO : **SLK2942T**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : 03.03.22
 TIME OF ACCIDENT : 18:20HRS

28	REAR BUZZER <i>Not in</i>	1	\$ 170.00	\$ 170.00	+
29	TAIL LAMP <i>cut</i>	2	\$ 520.00	\$ 1,040.00	✓
30	TAIL LAMP LOWER PANEL (OUTER) <i>2 pr</i>	2	\$ 272.00	\$ 544.00	+
31	TAIL LAMP INNER PANEL (LOWER) <i>1 pr</i>	2	\$ 199.00	\$ 398.00	+
32	REAR FENDER COWLING <i>Not in</i>	2	\$ 147.00	\$ 294.00	+
33	REAR FENDER INNER TRIM <i>LH could</i>	2	\$ 550.00	\$ 1,100.00	550 450
34	REAR FENDER AIR VENT <i>Not in</i>	2	\$ 58.00	\$ 116.00	+
35	REAR END PANEL <i>Dented</i>	1	\$ 920.00	\$ 920.00	681
36	REAR END PANEL TOP GARNISH <i>could</i>	1	\$ 155.00	\$ 155.00	✓
37	REAR FLOOR PANEL <i>Repair</i>	1	\$ 1,600.00	\$ 1,600.00	+
38	REAR FLOOR PANEL TOP OUTER COVER BOARD <i>could</i>	1	\$ 585.00	\$ 585.00	✓
39	REAR FLOOR PANEL TOP SIDE COVER BOARD <i>2 pr</i>	2	\$ 150.00	\$ 300.00	+
40	REAR FLOOR PANEL TOP INNER COVER BOARD <i>1 pr</i>	1	\$ 340.00	\$ 340.00	+
41	REAR STORAGE BOX (SPONGE) <i>Not in</i>	1	\$ 250.00	\$ 250.00	+
42	REAR STORAGE BOX (PLASTIC) <i>could</i>	1	\$ 495.00	\$ 495.00	✓
43	REAR TOOLS SPONGE TRAY <i>Not in</i>	1	\$ 185.00	\$ 185.00	+
44	REAR JACK COVER GARNISH <i>Not in</i>	1	\$ 190.00	\$ 190.00	✓
45	REAR JACK <i>Not in</i>	1	\$ 145.00	\$ 145.00	+
46	REAR CHASSIS FRAME LH <i>Repair</i>	1	\$ 550.00	\$ 550.00	+
47	REAR EXHAUST PIPE <i>2</i>	1	\$ 745.00	\$ 745.00	+
48	REAR EXHAUST INSULATOR <i>Not in</i>	1	\$ 195.00	\$ 195.00	+
49	REAR EXHAUST GASKET (SET) <i>Not in</i>	1	\$ 60.00	\$ 60.00	+
50	REAR EXHAUST MOUNTING	4	\$ 85.00	\$ 340.00	+

7651
6120.8

7556
5724.80

TOTAL PRICE \$ 20,089.60
 LESS 20% \$ 4,017.92
SUB TOTAL PRICE \$ 16,071.68

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Not in</i>	1	\$ 120.00	\$ 120.00	+
2	REAR BUMPER CLIP (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER EXHAUST COVER GARNISH CLIP (SET) <i>Not in</i>	1	\$ 30.00	\$ 30.00	+
4	TAIL GATE INNER TRIM CLIP (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00	30
5	TAIL GATE WINDSCREEN SEALANT <i>2 pr</i>	1	\$ 80.00	\$ 80.00	40
6	TAIL GATE WINDSCREEN INNER SEAL <i>Not in</i>	1	\$ 60.00	\$ 60.00	35
7	TAIL GATE WINDSCREEN INNER SOLAR FILM <i>Not in</i>	1	\$ 550.00	\$ 550.00	+
8	TAIL LAMP CLIP (SET) <i>Not in</i>	1	\$ 60.00	\$ 60.00	20
9	TAIL LAMP LOWER PANEL (OUTER) SEALANT <i>Not in</i>	2	\$ 80.00	\$ 160.00	+
10	TAIL LAMP INNER PANEL (LOWER) SEALANT <i>Not in</i>	2	\$ 80.00	\$ 160.00	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLK2942T**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : 03.03.22
 TIME OF ACCIDENT : 18:20HRS

11	REAR FENDER INNER COWLING (SET) <i>Me</i>	1	\$ 80.00	\$ 80.00	<i>x.</i>
12	REAR FENDER INNER TRIM CLIPS (SET) <i>Me</i>	1	\$ 80.00	\$ 80.00	<i>20</i>
13	REAR END PANEL INSULATION SEAL <i>Me</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
14	REAR END PANEL TOP GARNISH CLIP (SET) <i>Me</i>	1	\$ 40.00	\$ 40.00	<i>20</i>
15	REAR FLOOR PANEL INSULATION SEAL <i>Me</i>	1	\$ 350.00	\$ 350.00	<i>x.</i>
16	REVERSE SENSOR <i>David</i>	1	\$ 220.00	\$ 220.00	<i>20</i>

460

TOTAL \$ 2,300.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,400.00	<i>900</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	<i>1000</i>
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
5	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>x.</i>
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>✓</i>
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	<i>x</i>

2900

TOTAL \$ 5,360.00

Adrian Ly
L/S 04/03/22.

06 Days.

ESTIMATE REPORT

TOTAL PARTS COST : \$ 18,371.68
 TOTAL LABOUR COST : \$ 5,360.00
 TOTAL REPAIR COST : \$ 23,731.68

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 8780.80

L/S 7K

L/S 6HK

67K