

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III22002108/GVY3N2**Date:** 14/04/2022**REFERENCE**

Insured/Claimant:	COMFORTDELGRO DRIVING CENTRE PTE LTD	Policy No:	D20MFL0000637_02		
Date of Loss:	24/02/2022	Nature of Claim:	OD	Claim No:	MFL2022D0001189

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>FBN7900J</b>		Engine No:	LTA2002081
Make & Model:	YAMAHA Y125Z, 124cc		Chassis No:	LBPREF1023J0010592
Reg. Date:	10/12/2018 (Man. Year: 2018)		Odometer:	32801 km
Colour:	Red			
Engine Capacity:	124 cc			
Market Value/New Car Price:	S\$8,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	2.75-18	Rear Tyre Size:	2.75-18
Front Left Side:	Timsun 6 mm	Rear Left Side:	Timsun 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,142.25	1,110.75	31.50	2.76
Miscellaneous Items	1,060.00	1,060.00	0.00	0.00
Labour	400.00	380.00	20.00	5.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,602.25</b>	<b>2,550.75</b>	<b>51.50</b>	<b>1.98</b>
<b>- Excess (S\$)</b>	0.00	300.00	-300.00	
<b>(S\$)</b>	2,602.25	2,250.75	351.50	13.51
<b>+ GST 7.00/7.00% (S\$)</b>	182.16	157.55	24.61	13.51
<b>Nett Amount (S\$)</b>	<b>2,784.41</b>	<b>2,408.30</b>	<b>376.11</b>	<b>13.51</b>

**INSPECTION**

Date of Assignment:	07/03/2022	Present Location:	Kang Car Repairers Pte Ltd (HQ)
Date Inspected:	08/03/2022	Inspected At:	178 PAYA LEBAR ROAD
			#01-01
			REPAIRER: KANG CAR REPAIRERS PTE LTD
Estimated Period of Repair:	3.0 days		

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Apr 2022)	
<b>Parts:</b>	N/A	YAMAHA Y125Z 124cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBN7900J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER ASSY	Bent	65.00 FL	*65.00 FL
2	1		*STAY,FENDER 1	Bent	15.00 FL	*15.00 FL
3	1		*FRT FORK ASSY LH	Bent	420.00 FL	*420.00 FL
4	1		*FRT FORK ASSY RH	Bent	420.00 FL	*420.00 FL
5	1		*BRACKET, UNDER	Bent	120.00 FL	*120.00 FL
6	1		*BALL RACE KIT	Necessary	29.00 FL	*29.00 FL
7	2		*RETAINER, BALL BEARING	Necessary	20.00 FL	*20.00 FL
8	1		*CAST WHEEL, FRT	Cut	275.00 FL	*275.00 FL
9	1		*LEVER 2	Cut	12.50 FL	*12.50 FL
10	1		*LEVER 1	Cut	8.50 FL	*8.50 FL
11	4		*BOLT, HEX	Necessary	56.00 FL	*14.00 FL
12	1		*GRIP ASSY	Cut	12.00 FL	*12.00 FL
13	1		*RED LIGHT	Cut	35.00 FL	*35.00 FL
14	1		*ORANGE LIGHT	Distorted	35.00 FL	*35.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,523.00</b>	<b>1,481.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	380.75	370.25
<b>Total Parts (\$\$)</b>	<b>1,142.25</b>	<b>1,110.75</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	2	BEARING (Necessary)	10.00	10.00
2	1	FRT LOWER CRASHBAR (Cut)	400.00	400.00
3	1	FRT UPPER CRASHBAR (Cut)	400.00	400.00
4	1	LHR CRASHBAR (Cut)	250.00	250.00
Sub Total (\$\$)			1,060.00	1,060.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WHEEL ALIGHMENT	New	120.00	100.00
2	REPLACE ACCIDENT PARTS	New	280.00	280.00
Gross Labour Cost (\$\$)			400.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >