

QT22/PC9522XODC

<b>India International Insurance Pte Ltd</b>
64 Cecil Street
#04/#05 IOB Building
Singapore 049711

Dear Sir,

Cost of Repair to Vehicle PC9522X

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front bumper / BR	1	1,471.50	1,471.50
2.	Front bumper retainer LH ( upper & lower )	1 / MIS	256.00	256.00
3.	Front bumper clips / nec	10	2.50	20 25.00
4.	Front bumper center grille / BR	1	450.00	450.00
5.	Front panel / DD	1	3,545.80	3545.80
6.	Front windscreen / BR	1	2,988.60	2,988.60
7.	Front windscreen inner seal / nec	1	423.40	423.40
8.	Front LH headlamp upper cover / MIS	1	280.00	280.00
9.	Front grille cover / BR	1	350.00	350.00
10.	Front grille / BR	1	820.00	820.00
11.	Front grille clips / nec	10	2.50	10 25.00
12.	Reinforcement / X nn	1	1,200.70	1,200.70
13.	Front LH headlamp assy / BR	1	2,719.60	2,719.60
14.	Front LH headlamp bracket / DD	1	132.00	132.00
15.	Front LH corner panel / DD	1	587.90	587.90
16.	Front LH corner panel bracket / DD	1	245.50	245.50
17.	Front LH rear view mirror assy / BR	1	1,973.40	1,973.40
18.	Front LH side glass / BR	1	1,887.10	1,887.10

**CONNECT 3**  
566 Woodlands Road ( Mandai Estate ) Singapore 728697  
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L  
G S T : 5 3 3 6 0 0 6 1 L


19.	LH side panel / 00	1	2,987.32	2,987.32	
20.	Front LH lower inner pillar panel / 00	1	1,288.70	1,288.70	
21.	LH side inner trim / CUT	1	752.70	752.70	
22.	LH side inner garnish / CUT	1	569.20	569.20	
23.	Water tank (wiper) / CR4	1	175.00	175.00	
24.	Wiper arm LH X AN	1	85.00	85.00	
25.	Dashboard ? X AN	1	3,986.40	3,986.40	
26.	Front LH mud guard / CR4	1	335.10	335.10	
27.	Remove & refit dashboard (photo)	1	350.00	350.00	✓
28.	Remove & refit LH side glasses to assist repair (photo) 12 x 3	1	360.00	360.00	✓
29.	Remove & refit front windscreen	1	400.00	400.00	✓
30.	Sealant	8	40.00	320.00	✓
31.	Check wiring	1	100.00	90 100.00	
32.	Labour charges	1	1,800.00	1700 1,800.00	1590
33.	Spray painting	1	1,000.00	900 1,000.00	
EXTRA \$15 - net net			<b>SUB-TOTAL</b>	<b>SS33,890.92</b>	

- Price before 7% gst

Thank you.

Yours faithfully,

Winnie Chai  
HP: 9850-9666



Parts + Supp: \$26038.86(10%)  
labour \$3690  
total is \$29728.66.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Steve (LKK)

8/3/22, 10.10

ON MY AC  
EXPIR. ?

20 41

PIP

by RLH