



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2204348

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 15/07/2022
Reference CC3/CTI22002125/Tpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 6479C
Insured Veh. GBD 4208Y
Claim No. SNM22D201607/C02
Policy No. DMCVSNW00110872100
Accident Date 04/03/2022
Inspection Date 08/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref:	CC3/CTI22002125/Tpa3q2
3 ANSON ROAD #16-00			Date:	15/07/2022
SPRINGLEAF TOWERSINGAPORE 079909			Code:	CTI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 4208Y	Veh. Inspected	SHC 6479C	
Policy No.	DMCVSNW00110872100	Coverage (\$)	0.00	
Claim No.	SNM22D201607/C02	Excess (\$)	0.00	
Assign From		Assign Date	08/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5593368	Colour	SILVER	
Odometer	610396 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R15	HANKOOK	6 mm	
L/H Front Tyre	205/65 R15	HANKOOK	6 mm	
R/H Rear Tyre	205/65 R15	HANKOOK	6 mm	
L/H Rear Tyre	205/65 R15	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/03/2022	Inspection Date	08/03/2022	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6479C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	O/S TAIL LAMP	CRACKED	421.00	421.00
2	N/S & O/S REFLECTOR @\$350.00	NOT NECESSARY	700.00	-
1	BOOT LID	BENT	1,119.00	1,119.00
1	BOOT LID LOCK	NOT NECESSARY	99.00	-
1	BOOTLID STRIKER	NOT NECESSARY	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	CUT	96.00	96.00
1	BOOT LID LOWER GARNISH	NOT NECESSARY	290.00	-
2	BOOTLID HINGES @\$66.00	NOT NECESSARY	132.00	-
2	REAR LICENSE PLATE LAMP @\$30.00	NOT NECESSARY	60.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	190.00	-
1	END PANEL	NOT NECESSARY	250.00	-
1	END PANEL INNER GARNISH	NOT NECESSARY	74.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	DEFORMED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	NOT NECESSARY	58.00	-
1	REAR BUMPER INNER SPONGE	NOT NECESSARY	114.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	607.00	-
2	REAR BUMPER STAY O/S & N/S @\$54.00	NOT NECESSARY	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @ \$18.00	NOT NECESSARY	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @ \$18.00	NOT NECESSARY	36.00	-
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	NOT NECESSARY	92.00	-
	LESS 10% DISCOUNT		-546.10	-259.40
			4,914.90	2,334.60
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	30.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CC3/CTI22002125/Tpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	60.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	REAR NO PLATE WITH CASING (SN)	NOT NECESSARY	50.00	-
1	SEALANT (SN)	NOT NECESSARY	50.00	-
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			800.00	340.00
	LABOUR			
	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TOWING FEE.		50.00	50.00
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO HEAT/WELD ,CUT-OFF THE END PANEL,FLOORBOARD PANEL .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE REAR PANEL .		1,000.00	400.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID ,BOOTLID LOWER GARNISH ,REAR BUMPER ,END PANEL ,BOOTFLOOR.		1,000.00	500.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	30.00
			2,470.00	1,010.00
GRAND TOTAL			8,184.90	3,684.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CC3/CTI22002125/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 6479C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 6479C

RE-INSPECTION

