

ASS. REC. BY: TaughtREF: 003/CTI 22002125/T pas.**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 6479CYr Regn: 2015 / March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Optimac.c. 1685Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 610396

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNA 9M 414M F55 935 68Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R15R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hookhook

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 8/3/22Survey held at Premier Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

7-Mar-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC6479C

1 pc	o/s tail lamp @\$421.00	\$	421.00 <i>ing</i>
2 pcs	n/s & o/s reflector @\$350.00	\$	700.00 <i>X</i>
1 pc	Boot lid	\$	1,119.00 <i>by</i>
1 pc	Boot lid lock	\$	99.00 <i>X</i>
1 pc	Bootlid striker	\$	21.00 <i>X</i>
1 pc	Bootlid emblem	\$	27.00 <i>no</i>
1 pc	Bootlid CRDi	\$	29.00 <i>no</i>
1 pc	Boot lid rubber weatherstrip	\$	96.00 <i>cut</i>
1 pc	Boot lid lower garnish	\$	290.00 <i>?</i>
2 pcs	Bootlid hinges @ \$66.00	\$	132.00 <i>X</i>
2 pcs	Rear license plate lamp @ \$30.00	\$	60.00 <i>X</i>
1 pc	Bootlid inner trim	\$	190.00 <i>X</i>
1 pc	End panel	\$	250.00 <i>X</i>
1 pc	End panel inner garnish	\$	74.00 <i>X</i>
1 pc	Rear bumper	\$	696.00 <i>de</i>
1 pc	Rear bumper lower cover	\$	206.00 <i>de</i>
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 <i>?</i>
1 pc	Rear bumper inner sponge	\$	114.00 <i>?</i>
1 pc	Rear bumper reinforcement	\$	607.00 <i>?</i>
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00 <i>?</i>
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 <i>?</i>
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 <i>?</i>
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00 <i>X</i>
		\$	5,461.00
Less 10%		\$	546.10
		\$	4,914.90

7-Mar-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6479 C

S/NETT

1 set	Rear bumper clips	\$	48.00	30 net
1 set	End panel inner garnish clips	\$	30.00	X
1 set	Bootlid inner trim clips	\$	52.00	X
1 set	Bootlid lower garnish clips	\$	60.00	X
1 set	Bootlid stickers	\$	100.00	60 net
1 set	Reverse sensor	\$	280.00	200 net
1 pc	Rear bumper top protector	\$	80.00	50 net
1 pc	Rear no. plate with casing	\$	50.00	X
1 pc	Sealant	\$	50.00	X
	Sundry	\$	50.00	X
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
	Towing fee	\$	50.00	X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	40? photo
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel,. Including knock-out, straighten, repair, reshape and adjust of the rear panel	\$	1,000.00	400
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, bootfloor	\$	1,000.00	500
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	30
		<u>\$</u>	<u>8,184.90</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphun 97495749
WP 8/3/22 @ 3pm
03 days
Tanphun @ Kuantan
4/5 Resurvey after repair.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	19 Mar 2015 / 10:32:30	Receipt No:	AACCK001-AX239-150319-000024
Asset Type:	Vehicle	Transaction Amount:	\$65,578.00
Asset ID:	SHC6479C	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150319103230353638		
Vehicle No.:	SHC6479C		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	19 Mar 2015		
Original Registration Date:	19 Mar 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5593368		
Engine No.:	D4FDEH313386		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$21,318.00		
Minimum PARF Benefit:	\$8,607.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	19 Mar 2015 10:32:30		
COE No.:	2015031901002284E		
COE Expiry Date:	18 Mar 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$51,092.00		
Lifespan Expiry Date:	18 Mar 2023		



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717
TEL : 6743 1987 (3 LINES) FAX : 6743 0013
Email: peoplevehicle@gmail.com
Reg No: 200415052W



Date: 4/3/22

CASH SALE/WORK ORDER No: PE 5534

賣號

Messrs: Panto P17

車號

Vehicle No: SHC6479C

車型

Model No: Optima 2

由

From: BHC632 Senja Rd

到

To: Omega Level 1

其他

Remark: 97891070

時間

Time: 20:46:21:58:23:00

AMOUNT: \$ 50

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by: [Signature]

收貨人

Received by: [Signature]

- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ Jump Start
- ☐ Changing of Battery
- ☐ Tyre Replacement/ Patching
- ☐ Crane Up/Winch Out
- ☐ With Load/Cargo Box
- ☐ Flat Bed
- ☐ King Dolly to lift up
- ☐ Low Body Kit
- ☐ Repo
- ☐ Door Opening Service
- ☐ Collect Document/Key
- ☐ Jurong Island/Cargo Complex
- ☐ Woodlands/Tuas Checkpoint
- ☐ Cancellation Charge (Reach Location)
- ☐ Cancellation Charge (After 15 minutes)