

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

7-Mar-22

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC6479C

1 pc	o/s tail lamp @\$421.00	\$	421.00	ing ✓
2 pcs	n/s & o/s reflector @\$350.00	\$	700.00	X n ✓
1 pc	Boot lid	\$	1,119.00	bt ✓
1 pc	Boot lid lock	\$	99.00	X n ✓
1 pc	Bootlid striker	\$	21.00	X n ✓
1 pc	Bootlid emblem	\$	27.00	de ✓
1 pc	Bootlid CRDi	\$	29.00	de ✓
1 pc	Boot lid rubber weatherstrip	\$	96.00	cut ✓
1 pc	Boot lid lower garnish	\$	290.00	X ✓
2 pcs	Bootlid hinges @ \$66.00	\$	132.00	X ✓
2 pcs	Rear license plate lamp @ \$30.00	\$	60.00	X ✓
1 pc	Bootlid inner trim	\$	190.00	X ✓
1 pc	End panel	\$	250.00	X ✓
1 pc	End panel inner garnish	\$	74.00	X ✓
1 pc	Rear bumper	\$	696.00	de ✓
1 pc	Rear bumper lower cover	\$	206.00	de ✓
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	X ✓
1 pc	Rear bumper inner sponge	\$	114.00	X ✓
1 pc	Rear bumper reinforcement	\$	607.00	X ✓
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	X ✓
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	X ✓
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	X ✓
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	X ✓
		\$	5,461.00	
Less 10%		\$	546.10	
		\$	4,914.90	

2594  
2334.60

7-Mar-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6479 C

S/NETT

1 set	Rear bumper clips	\$	48.00 30ne
1 set	End panel inner garnish clips	\$	30.00 X 7
1 set	Bootlid inner trim clips	\$	52.00 X 1
1 set	Bootlid lower garnish clips	\$	60.00 X 1
1 set	Bootlid stickers	\$	100.00 60ne
1 set	Reverse sensor	\$	280.00 200ne
1 pc	Rear bumper top protector	\$	80.00 50ne
1 pc	Rear no. plate with casing	\$	50.00 X 1
1 pc	Sealant	\$	50.00 X 1
			340
	Sundry	\$	50.00 X 1
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
	Towing fee	\$	50.00 X 1
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 40 8 plus
	To labour charge for dismantle and renew the accident damaged parts: To heat/weld, cut-off the the end panel, floorboard panel, Including knock-out, straighten, repair, reshape and adjust of the rear panel	\$	1,000.00 400
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, bootfloor	\$	1,000.00 500
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 30
		\$	8,184.90 1010

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphun 97495749  
WP 8/3/22 R 3pm  
03 days  
Tanphun @ LKK Auto Consultants  
4/5 Resurvey after repair.

2334.60

340

1010

3684.60

4/5 2900

03 days