

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6548 8156

Our Job Ref No : 305505018
Date : 19/02/22

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHC1008L

Date of Accident : 15.02.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SGV7910D
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges (include advertisement stickers etc,if any) _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: <u>20%</u>	<u>\$1,100.00</u>
Final Lumpsum Repair cost	<u>\$1,100.00</u>

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as **Correct and Confirmed** if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : THEVAN

Tel : 62148398

Date : 16/3/22

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REG. NO: Thuvan / "LIC: NIL

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 17-Feb-22

INSURANCE: NTUC (L/S)

MODEL: Hyundai i40

MVA: LIM T S

VEHICLE NO.: SHC1008L

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$553.00 / <u>cut</u>
	Rear Bumper Under Cover	1		\$228.00 / <u>scr</u>
	Rear Bumper Sponge	1		\$119.50 / <u>XSUC</u>
	Rear Bumper Reinforcement	1		\$428.40 / <u>XSUC</u>
	Rear Bumper Clips	10	\$2.20	\$22.00 / <u>MC</u>
	Rear Bumper Reflector <u>(RH/LH) XSUC</u>	2	\$32.00 / <u>MC</u>	\$64.00 / <u>XSUC</u>
SUB TOTAL				\$1,414.90
LESS 20%				\$282.98
DISCOUNTED TOTAL				\$1,131.92
	Reverse Sensors	1		\$135.70 / <u>cut</u>
NETT SUB				\$135.70
LESS 10%				\$13.57
NETT TOTAL				\$122.13
SPARE PARTS TOTAL				\$1,254.05
Labour Charge				
	Panel Beating			\$300.00 / <u>280</u>
	Spray Painting Charge			\$300.00 / <u>250</u>
	R/I Reverse Sensors			\$120.00 / <u>30</u>
TOTAL LABOUR				\$720.00
ESTIMATE TOTAL				\$1,974.05

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuvan 82235769
 17/2/22 1630
 L/S after repair photo
 2 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: