

Our Job Ref No : 305505040
Date : 19/02/22

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHD7165X

Date of Accident : 16.02.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- PA4822Z

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (include advertisement stickers etc,if any)

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$1,400.00

Final Lumpsum Repair cost \$1,400.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : THEVAN

Tel : 62148398

Date : 16/3/22

Fax : 65468156

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|----------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | --- | N | | |
| 3. Survey Fees | ----- | -- | | |
| 4. LTA Search Fee | \$7.49 /\$2.00 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 17-Feb-22MODEL: Hyundai i40VEHICLE NO.: SHD7165XINSURANCE: NTUC CLSMVA: LIM T S

| PART NO. | DESCRIPTION | QTY | UNIT PRICE | AMOUNT |
|----------|---------------------------------|-----|------------|------------|
| | Front Bumper | 1 | | \$1,052.20 |
| | Front Bumper Clips | 10 | \$2.20 | \$22.00 |
| | Radiator Grille | 1 | | \$1,480.00 |
| | Radiator Grille H Emblem | 1 | | \$129.50 |
| | SUB TOTAL | | | \$2,683.70 |
| | LESS 20% | | | \$536.74 |
| | DISCOUNTED TOTAL | | | \$2,146.96 |
| | Front No. Plate with Trim Cover | 1 | | \$55.00 |
| | SUB S/NETT | | | \$55.00 |
| | LESS 10% | | | \$5.50 |
| | SUB S/NETT TOTAL | | | \$49.50 |
| | SPARE PARTS TOTAL | | | \$2,196.46 |
| | <u>Labour Charge</u> | | | |
| | Panel Beating | | | \$300.00 |
| | Spray Painting Charge | | | \$300.00 |
| | TOTAL LABOUR | | | \$600.00 |
| | ESTIMATE TOTAL | | | \$2,796.46 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan @ Comfort - 10m
 8223 5769
 17/2/22 1700
 L/S after repair photo
 2 days swp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: