

507198P

Our Job Ref No : 305504853  
Date : 17/02/22

**COMFORTDELGRO  
ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHA1670J

10/02/22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SND8372L
2. The finalized amount shall be:
- (a) Spare Parts after List discount \_\_\_\_\_
- (b) Labour Charges \_\_\_\_\_
- Total for Part-By-Part Repair Cost** \_\_\_\_\_
- (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \$1,100.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and  
finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : THEVAN

Date : 14/3/22

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

## REPAIR ESTIMATE\*

VEHICLE NO SHA1670L  
 MAKE REG: 05.01.2017  
 MODEL HYU- I40

10/02/22

Type

CHIANG/ NTUC

Qty	Parts Description/ Labour	Unit Price	Amount	
1	REAR BUMPER COVER		\$553.00	✓ CUL
1	REAR BUMPER LOWER COVER		\$228.00	✓ SC
10	REAR BUMPER CLIPS	\$2.20	\$22.00	✓ N/C
1	REAR BUMPER BRACKET LH		\$35.60	✓ N/C
1	REAR BUMPER REINFORCEMENT		\$428.40	7. X50C
1	REAR BUMPER REFLECTOR LH		\$32.00	7. X50C
	<b>SUB TOTAL</b>		<b>\$1,299.00</b>	
	20.00%		\$259.80	
	<b>DISCOUNTED TOTAL</b>		<b>\$1,039.20</b>	
1	REAR REVERSE SENSOR		\$135.70	✓ CUL
1	REAR BUMPER PROTECTOR		\$50.00	✓ N/C
			<b>\$167.13</b>	
	<b>Labour Charge</b>		\$420.00	280
	Panel Beating		\$300.00	250
	Spray Painting Charge		\$60.00	20
	Remove/refix reverse sensor		\$40.00	20
	Check Lighting & Wiring		<b>\$820.00</b>	
	<b>TOTAL LABOUR</b>			
	<b>ESTIMATE TOTAL</b>		<b>\$2,026.33</b>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan

82235769

14/2/22 1600

45 after repair photo

2 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: