

ASS. REC. BY:

Steve

REF:

CC4/GRB 22002133/ga3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SMT 2338D

Yr Regn:

16/3/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 116D

c.c. 1496

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

69994

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WRAIV72081V775535

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size:

F:

225/45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or .

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

4/3/22

D.O.I.

29/3/22

Survey held at

Performance Motors

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-75K

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + R.S. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.J. (\$

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

04.03.2022

RO-164676



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 61115
Date Estimated : 07/03/2022
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

SAMEER MITTAL
1 Amber Gardens
#03-03 One Amber

Singapore 439957

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMT2338D	WBA1V72080V725535	16/03/2017	116d	67822

DESCRIPTION	VALUE
To replace rear bumper including to knock out boot lid and dented area	1790 - 2,550.00
To respray rear bumper and boot lid	1828 - 1,923.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 - 177.00
To check electrical wiring system and lighting at the rear section for proper function.	168 - 177.00
Sundries.	80.00

Total Labour 1: **4,907.00**

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER	1	418.55	418.55
REAR BUMPER CENTRE GUIDE (M)	1	153.50	153.50
# REAR BUMPER TOWING EYE COVER	1	39.35	39.35
# REAR BUMPER RH MOUNT	1	141.05	141.05
# REAR BUMPER PRIMED (RFC)	1	1,004.85	1,004.85
REAR PDC HOLDER SET	1	25.75	25.75
EMBLEM GROMMET	2	0.95	1.90
# Heat insulat	1	73.60	73.60
PLAQUE 82MM	1	72.85	72.85
# RH REFLECTOR	1	37.90	37.90
NUMBER PLATE LIGHT LED	2	28.15	56.30
DECOUPLING RING PDC TORQUE CONVERTE	1	5.15	5.15
PDC SENSOR MINERALWEISS (A96)	1	371.20	371.20
(DG/SL) ADHESIVE SET K6	1	53.05	53.05

Total Parts : **2,455.00**

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559K GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Raffles Avenue Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796661 (AfterSales)
64796662 (Motors)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 61115
Date Estimated : 07/03/2022
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMT2338D	WBA1V72080V725535	16/03/2017	116d	67822

W L P L
P/P
29/3/22, 12.00r
h PL 11
- 5 yr-

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	4,907.00
Parts	:	2,455.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	515.34
Grand Total	:	7,877.34

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **