

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 61115**  
Date Estimated : **07/03/2022**  
Prepared By : **Foong Shiuh Jye**

**- ESTIMATE REPAIR FOR -**  
**SAMEER MITTAL**  
**1 Amber Gardens**  
**#03-03 One Amber**

**Singapore 439957**

**- ACCOUNT - 219**  
**India Int'L Insurance Pte Ltd**  
**64 Cecil Street**  
**#04-05 IOB Building**  
**Singapore 049711**

|                 |                        |                   |             |              |
|-----------------|------------------------|-------------------|-------------|--------------|
| REGN. NO.       | CHASSIS NO.            | REGN. DATE        | MODEL       | MILEAGE      |
| <b>SMT2338D</b> | <b>WBA1V72080V7255</b> | <b>16/03/2017</b> | <b>116d</b> | <b>69994</b> |

| DESCRIPTION                                                                                                                | ORIGINAL PRICE | DISC. % | NETT     |
|----------------------------------------------------------------------------------------------------------------------------|----------------|---------|----------|
| To replace rear bumper including to knock out boot lid and dented area                                                     | 1,700.00       | 0.00    | 1,700.00 |
| To respray rear bumper and boot lid                                                                                        | 1,826.00       | 0.00    | 1,826.00 |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function. | 168.00         | 0.00    | 168.00   |
| To check electrical wiring system and lighting at the rear section for proper function.                                    | 168.00         | 0.00    | 168.00   |
| Sundries.                                                                                                                  | 80.00          | 0.00    | 80.00    |

| DESCRIPTION                         | UNIT PRICE | QTY  | DISC. % | NETT     |
|-------------------------------------|------------|------|---------|----------|
| REAR BUMPER CARRIER                 | 418.55     | 1.00 | 0.00    | 418.55   |
| REAR BUMPER CENTRE GUIDE (M)        | 153.50     | 1.00 | 0.00    | 153.50   |
| REAR BUMPER PRIMED (RFC)            | 1,004.85   | 1.00 | 0.00    | 1,004.85 |
| REAR PDC HOLDER SET                 | 25.75      | 1.00 | 0.00    | 25.75    |
| PLAQUE 82MM                         | 72.85      | 1.00 | 0.00    | 72.85    |
| NUMBER PLATE LIGHT LED              | 28.15      | 2.00 | 0.00    | 56.30    |
| DECOUPLING RING PDC TORQUE CONVERTE | 5.15       | 1.00 | 0.00    | 5.15     |
| (DG/SL) ADHESIVE SET K6             | 53.05      | 1.00 | 0.00    | 53.05    |

### # SUPPLEMENTARY ITEMS

|                                 |          |
|---------------------------------|----------|
| Total Labour :                  | 3,942.00 |
| Total Parts :                   | 1,790.00 |
| Total Labour & Parts :          | 5,732.00 |
| Deduction for Excess :          |          |
| Total Repair Costs less Excess: | 5,732.00 |
| GST @7%:                        | 401.24   |
| Grand Total :                   | 6,133.24 |

LOSS OF USE=\$120X5  
LTA SEARCH FEE=\$7.45