

TTS Eurocars Pte Ltd (Co.Reg.No:200413930H)

383 Sin Ming Drive, TTS Centre

Singapore 575717

Tel: 6757 2622 / 6842 2222 Fax: 6741 1626 Email: bernardtham@tts.com.sg;jenniferchoo@tts.com.sg

(SUPPLEMENTARY)INSURER: **HL Assurance Pte Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MP306385	Date of Loss:	03/03/2022
Vehicle Reg. No.:	SKR8088U	Driveable?	
Driver Age/Info:	23 / MALE	Party At Fault:	DRIVER
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	SHANMUGARATNAM S/O ERAMPAMOORTHY	Contact No:	+6596957077
Driver:	LARVINESEHN SHANMUGARATNAM		
Make/Model:	MERCEDES-BENZ E200 (R17), 2.0 (A)	Vehicle Reg. Date:	20/10/2017
Vehicle Colour:	BLACK		
Engine No:	65492080128331	Chassis No:	WDD2130132A271912
Odometer:	114136 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	30		
Description of Accident/Loss	COLLISION- REAR TO SIDE		
Present Location:	TTS EUROCARS PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	1,018.75
Miscellaneous Items	270.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	1,288.75
+ GST 7.00% (\$)	90.21
Nett Amount (\$)	1,378.96
+ Previous Estimates (\$)	21,489.61
Claim Total (\$)	22,868.57

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Aug 2022)

Parts: 143 MERCEDES-BENZ E200 (R17) 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: TTS Eurocars Pte Ltd/SKR8088U/18/08/2022 10:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WEATHERSTRIP ON BODY repeated	0.00	0.00	*145.00 F
2	1		*TRIM SEAT BASE cut	0.00	0.00	*265.00 F
3	1		*MIRROR SHELL cracked	0.00	0.00	*120.00 F
4	1		*DOOR TRIM STRIP cracked	0.00	0.00	*85.00 F
5	1		*ORNAMENTAL deformed	0.00	0.00	*100.00 F
6	1		*BEARING BRACKET cracked	0.00	0.00	*100.00 F

F=Franchise part.

Sub Total (S\$)	815.00
+ Margin on L,N Items 25.00% (S\$)	203.75
Total Parts (S\$)	1,018.75

TTS Eurocars Pte Ltd/SKR8088U/18/08/2022 10:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REPAIR RHF SEAT BELT nec	135.00
2	1	REPAIR RHR SEAT BELT nec	135.00
Sub Total (\$\$)			270.00

Estimates on Labour

There are no labour items selected.

TTS Eurocars Pte Ltd/SKR8088U/18/08/2022 10:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >