



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2201526

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/03/2022
Reference CC3/CTI22002142/Tpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 2879T
Insured Veh. SMX 5679D
Claim No. SNM22D201650/C02
Policy No.
Accident Date 02/03/2022
Inspection Date 03/03/2022

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (7%)	19.60
Grand Total	299.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22002142/Tpa3q2 Date: 17/03/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMX 5679D	Veh. Inspected	SHA 2879T
	Policy No.		Coverage (\$)	0.00
	Claim No.	SNM22D201650/C02	Excess (\$)	0.00
	Assign From		Assign Date	03/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHC851CVLU186567	Colour	BLUE
	Odometer	253338 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/03/2022	Inspection Date	03/03/2022
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2879T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	459.40	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	NOT NECESSARY	451.25	-
1	ANTENNA SMARTKEY	NOT NECESSARY	40.50	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
	LESS 20% DISCOUNT		-234.93	-4.40
			939.72	17.60
	<u>SPECIAL NETT ITEMS</u>			
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
			380.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER .		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK ALL LIGHTING.	NOT NECESSARY	60.00	-
	REMOVE /REFIX REVERSE SENSOR .		80.00	30.00
			840.00	630.00
	GRAND TOTAL		2,159.72	847.60
	RECOMMENDED COST OF REPAIRS			847.60

Report Ref No. CC3/CTI22002142/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 2879T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 2879T

RE-INSPECTION

