AFORT TRANSPORTATION PTE LTD

PAIR ESTIMATE

√ehicle No.: SHA2879T

Make

: HYUNDAI

Model

: IONIQ(G2)

Date: 03/03/22

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY	N	*	\$451.25
1	ANTENNA SMARTKEY		nt	7 × \$40.50
1	REAR BUMPER FOG LAMP			LX \$201.50
				l l
	SUB TOTAL		22 17-60	\$1,174.65
	LESS 20%	σ	/	\$234.93
	DISCOUNTED TOTAL		17-60	\$939.72
	REAR FENDER ADVERTISEMENT LOGO RH			ne - \$100.00
1	REAR FENDER ADVERTISEMENT LOGO LH			\$100.00
1	REAR BUMPER REVERSE SENSOR		200	WAX \$180.00
ľ	NEW TOTAL ENTREMENT OF THE PROPERTY OF THE PRO		-	\$380.00
				\$000.00
ļ	abour Charge			
F	PANEL BEATING			35 \$400.00
5	SPRAY PAINTING CHARGE			250 \$300.00
c	CHECK ALL LIGHTING		ên -	nn ×\$60.00
F	REMOVE/REFIX REVERSE SENSOR		630	30 \$80.00
1	TOTAL LABOUR			\$840.00
			\$242.60	
	ESTIMATE TOTAL		1017.60	\$2,159.72
			\$847.60 02days #	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ranfler 97495749

W/ 3/3/2205pm

2 days

pesury run parts

fanfleric (hhantom

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: