

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAPHIC IMAGE SOLUTIONS PTE LTD
50 BUKIT BATOK ST 23 #07-17 MIDVIEW
BUILDING
SINGAPORE 659578

Contact : 88232210

TAX INVOICE

Repair Code : CLM17116

Date in : 07/03/2022

Vehicle Num. : SMJ4881R

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11312501/L15B5562519

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BONNET <i>Dented</i>	1	892.30	✓ 892.30
FRONT BONNET HINGES L/R <i>new</i>	2	48.50	+ 97.00
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R <i>2</i>	2	23.80	+ 47.60
FRONT BONNET INNER SIDE MOULDING L/R	2	37.50	+ 75.00
FRONT BONNET INNER TOP MOULDING L/R <i>new</i>	2	33.00	+ 66.00
FRONT BONNET MECHANISM LOCK	1	95.00	+ 95.00
FRONT BUMPER <i>Dented</i>	1	927.50	765 927.50
FRONT BUMPER FOGLAMP GARNISH L/R <i>new</i>	2	45.00	+ 90.00
FRONT BUMPER LOWER GRILLE <i>new</i>	1	77.50	+ 77.50
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	321.00	✓ 321.00
FRONT BUMPER REINFORCEMENT TOP MOULDING L/R <i>new</i>	2	35.00	+ 70.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	20.60	+ 41.20
FRONT BUMPER TOW HOOK COVER <i>new</i>	1	17.10	+ 17.10
FRONT FENDER ARCH GARNISH L/R <i>new</i>	2	165.00	+ 330.00
FRONT GRILLE <i>cracked</i>	1	351.80	✓ 351.80
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	23.40	- 23.40
FRONT GRILLE CENTER BRACKET <i>cracked</i>	1	76.00	✓ 76.00
FRONT GRILLE OUTER COVER <i>cracked</i>	1	421.00	✓ 421.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAPHIC IMAGE SOLUTIONS PTE LTD
50 BUKIT BATOK ST 23 #07-17 MIDVIEW
BUILDING
SINGAPORE 659578

Contact : 88232210

TAX INVOICE

Repair Code : CLM17116

Date in : 07/03/2022

Vehicle Num. : SMJ4881R

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11312501/L15B5562519

FRONT GRILLE TOP GARNISH <i>could</i>	1	85.00	✓	85.00
FRONT HEADLAMP CHROME MOULDING L/R <i>new</i>	2	108.90	+	217.80
FRONT HEADLAMP L/R <i>could</i>	2	1715.40	✓	3,430.80
FRONT HEADLAMP LOWER BRACKET L/R <i>could</i>	2	35.00	-	70.00
FRONT HEADLAMP SIDE BRACKET L/R <i>new</i>	2	35.00	+	70.00
FRONT HORN <i>new</i>	1	110.50	+	110.50
FRONT TOP PANEL <i>Repair</i>	1	176.90	+	176.90
Subtotal before discount				8,180.40
Percentage discount 20%				1,636.08
Sub-total 1				6,544.32
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	30	50.00
FRONT FENDER ARCH GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	+	60.00
FRONT GRILLE CLIPS - SET <i>new</i>	1	50.00	20	50.00
FRONT NUMBER PLATE <i>Set</i>	1	25.00	✓	25.00
FRONT NUMBER PLATE HOLDER <i>Set</i>	1	50.00	30	50.00
Subtotal before discount				235.00
Percentage discount 0%				0.00
Sub-total 2				235.00
Parts-total				6,779.32

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAPHIC IMAGE SOLUTIONS PTE LTD
50 BUKIT BATOK ST 23 #07-17 MIDVIEW
BUILDING
SINGAPORE 659578

Contact : 88232210

TAX INVOICE

Repair Code : CLM17116

Date in : 07/03/2022

Vehicle Num. : SMJ4881R

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11312501/L15B5562519

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

1,610.00

8,389.32

*** This is a computer-generated document which requires no signature.***

page 3

Adnan L
h/s 08/03/22

04 Days

total: 6314.04

h/s: SK ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: