

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHIN KHAI CONSTRUCTION PTE LTD
 27 KAKI BUKIT CRESCENT KAKI BUKIT
 TECHPARK 1
 SINGAPORE 416258

Contact : 87543132, 96759767

*TP Chian.
Xiao Chan.*

TAX INVOICE

Repair Code : CLM17114
 Date in : 07/03/2022
 Vehicle Num. : SLN5015J
 Model : HONDA CITY 1.5 SV CVT
 Chassis/Eng# : MRHGM6660HT000129/L15Z14118254

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Distorted</i>	1	622.30	✓ 622.30
REAR BOOTLID 'CITY' EMBLEM	1	21.90	✓ 21.90
REAR BOOTLID 'I-VTEC' EMBLEM	1	21.90	✓ 21.90
REAR BOOTLID 'LOGO' EMBLEM	1	31.80	✓ 31.80
REAR BOOTLID HINGES L/R <i>Best</i>	2	79.80	✓ 159.60
REAR BOOTLID INNER RUBBER STOPPER (LONG) L/R <i>new</i>	2	20.00	+ 40.00
REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i>	2	9.80	+ 19.60
REAR BOOTLID INNER TRIM BOARD <i>form</i>	1	99.70	✓ 99.70
REAR BOOTLID LOCK STRIKER <i>new</i>	1	39.40	+ 39.40
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	105.20	✓ 105.20
REAR BOOTLID NUMBER PLATE LAMP L/R <i>new</i>	2	28.40	+ 56.80
REAR BOOTLID OUTER CHROME HANDLE <i>new</i>	1	165.20	✓ 165.20
REAR BOOTLID OUTER LOCK SWITCH WITH CAMERA <i>new</i>	1	625.90	✓ 625.90
REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R <i>new</i>	2	25.00	✓ 50.00
REAR BOOTLID REFLECTOR L/R <i>new</i>	2	98.60	✓ 197.20
REAR BOOTLID WEATHER STRIP <i>new</i>	1	84.20	✓ 84.20
REAR BUMPER <i>Distorted</i>	1	463.70	✓ 463.70
REAR BUMPER REFLECTOR L/R <i>new</i>	2	48.20	✓ 96.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHIN KHAI CONSTRUCTION PTE LTD
 27 KAKI BUKIT CRESCENT KAKI BUKIT
 TECHPARK 1
 SINGAPORE 416258

Contact : 87543132, 96759767

TAX INVOICE

Repair Code : CLM17114
 Date in : 07/03/2022
 Vehicle Num. : SLN5015J
 Model : HONDA CITY 1.5 SV CVT
 Chassis/Eng# : MRHGM6660HT000129/L15Z14118254

REAR BUMPER SIDE RETAINER L/R	<i>could</i>	2	23.90	✓	47.80
REAR END PANEL	<i>Distorted</i>	1	395.80	✓	395.80
REAR END PANEL ANTENNA SENSOR	<i>could</i>	1	78.10	✓	78.10
REAR END PANEL BUZZLE SENSOR	<i>could</i>	1	95.20	✓	95.20
REAR END PANEL INNER TOP GARNISH	<i>could</i>	1	86.20	✓	86.20
REAR EXHAUST GASKET	<i>new</i>	1	19.20	+	19.20
REAR EXHAUST RUBBER MOUNTING	<i>given</i>	2	18.70	+	37.40
REAR EXHAUST SILENCER BOX	<i>given</i>	1	580.20	+	580.20
REAR FENDER INNER PANEL L/R	<i>Repair</i>	2	459.20	+	918.40
REAR FENDER INNER SHIELD L/R	<i>tom</i>	2	149.80	✓	299.60
REAR FENDER INNER TRIM BOARD L/R	<i>tom</i>	2	99.30	✓	198.60
REAR FENDER L/R	<i>RT Buckled</i>	2	1109.40	✓	2218.80
REAR FLOOR LOWER JACK PANEL	<i>Buckled</i>	1	289.00	✓	289.00
REAR FLOOR PANEL	<i>Buckled</i>	1	560.20	✓	560.20
REAR FLOOR PANEL TOP BOARD COVER	<i>tom</i>	1	129.40	✓	129.40
REAR TAILLAMP INNER BLACK GASKET L/R	<i>new</i>	2	25.00	-	50.00
REAR TAILLAMP INNER PANEL L/R	<i>Buckled</i>	2	92.70	-	185.40
REAR TAILLAMP INNER VERTICAL PANEL L/R	<i>Buckled</i>	2	269.00	✓	538.00

1109.40
~~2218.80~~
179.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHIN KHAI CONSTRUCTION PTE LTD
 27 KAKI BUKIT CRESCENT KAKI BUKIT
 TECHPARK 1
 SINGAPORE 416258

Contact : 87543132, 96759767

TAX INVOICE

Repair Code : CLM17114

Date in : 07/03/2022

Vehicle Num. : SLN5015J

Model : HONDA CITY 1.5 SV CVT

Chassis/Eng# : MRHGM6660HT000129/L15Z14118254

REAR TAILLAMP L/R <i>combed</i>	2	325.70	✓ 651.40
REAR WINDSCREEN <i>let</i>	1	739.20	✓ 739.20
REAR WINDSCREEN MOULDING <i>Nu</i>	1	149.80	✓ 149.80
Subtotal before discount			11,168.50
Percentage discount 20%			2,233.70
Sub-total 1			8,934.80
REAR BOOTLID 'LOGO' EMBLEM CLIPS - SET <i>Nu</i>	1	30.00	<i>10</i> 30.00
REAR BOOTLID INNER TRIM BOARD CLIPS - SET <i>Nu</i>	1	50.00	<i>20</i> 50.00
REAR BOOTLID NUMBER PLATE <i>Best</i>	1	25.00	✓ 25.00
REAR BOOTLID NUMBER PLATE HOLDER <i>Deland</i>	1	50.00	<i>30</i> 50.00
REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET <i>Nu</i>	1	50.00	<i>20</i> 50.00
REAR BUMPER CLIPS - SET <i>Nu</i>	1	80.00	<i>30</i> 80.00
REAR BUMPER REVERSE SENSOR (4PC) - SET <i>Parad</i>	1	400.00	<i>300</i> 400.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Nu</i>	1	40.00	<i>10</i> 40.00
REAR FENDER INNER SHIELD CLIPS L/R - SET <i>Nu</i>	2	50.00	<i>20</i> 100.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>Nu</i>	2	50.00	<i>60</i> 100.00
REAR FLOOR PANEL INSULATOR MAT - SET <i>Nu</i>	1	300.00	<i>200</i> 300.00
REAR TAILLAMP CLIPS L/R - SET <i>Nu</i>	2	30.00	<i>20</i> 60.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHIN KHAI CONSTRUCTION PTE LTD
 27 KAKI BUKIT CRESCENT KAKI BUKIT
 TECHPARK 1
 SINGAPORE 416258

Contact : 87543132, 96759767

TAX INVOICE

Repair Code : CLM17114
 Date in : 07/03/2022
 Vehicle Num. : SLN5015J
 Model : HONDA CITY 1.5 SV CVT
 Chassis/Eng# : MRHGM6660HT000129/L15Z14118254

REAR WINDSCREEN SEALANT <i>Mr</i>	1	80.00	<i>60</i>	80.00
Subtotal before discount				1,365.00
Percentage discount 0%				0.00
Sub-total 2				1,365.00
Parts-total				10,299.80

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.			<i>✓</i>	80.00
to remove, reinstall windscreen (REAR)			<i>120</i>	150.00
To remove, reinstall petrol tank. (to FR)			<i>60</i>	80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)			<i>60</i>	120.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.			<i>1200</i>	1,400.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.			<i>60</i>	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.			<i>3330</i>	1600 2,200.00
To apply anti-rust chemical on repaired and replaced panel.			<i>100</i>	120.00
To transfer rear bootlid mechanism lock outer handle reflector			<i>50</i>	80.00
Labour Total				4,330.00
Parts & Labour Total				14,629.80

Admin Li
L/c 08/03/22

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

12 Pages
Tolani 1052676
L/c J. HK ✓