

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22002151/Kty3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	09/05/2022	
			Code	: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJB 9328S	Veh. Inspected	SMP 3973J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10013996/EE	Excess (\$)	0.00	
	Assign From	SHAFAWATI	Assign Date	08/03/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES GLA180 (A)	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	WDC1569422J653277	Colour	METALLIC BLACK	
	Odometer	80736 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	235/50 R18	YOKOHAMA	7 mm	
	L/H Front Tyre	235/50 R18	YOKOHAMA	7 mm	
	R/H Rear Tyre	235/50 R18	YOKOHAMA	7 mm	
	L/H Rear Tyre	235/50 R18	YOKOHAMA	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/02/2022	Inspection Date	08/03/2022	
	Survey held at	TONG LUCK AUTO PL			
		160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	ib. Estimate Days of Repair				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: