



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 02/03/2022

TP Veh Reg No: GBD6734G

Estimate No: ES2100142

Date: 07 Mar 2022

Policy No:

Veh Reg No: SJY6020C

Make/Model: TOYOTA VIOS E AUTO

Chassis No: MR053HY9305169795

Engine No: 1NZY106637

Reg. Date: 17/09/2010

Estimate Repair Cost to Vehicle No: SJY6020C

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR NUMBER PLATE	50.00	1 PC	50.00	45.00
2 REVERSE SENSORS	300.00	1 PC	300.00	200.00
			350.00	350.00
Spare Parts				
3 BOOT EMBLEM 'LOGO'	83.50	1 PC	83.50	✓
4 BOOT EMBLEM 'VIOS'	73.50	1 PC	73.50	✓
5 BOOT EMBLEM 'E'	73.50	1 PC	73.50	✓
6 BOOT HINGE - LH	100.00	1 PC	100.00	X
7 BOOT HINGE - RH	100.00	1 PC	100.00	X
8 BOOT LOCK	185.10	1 PC	185.10	✓
9 BOOT OUTER GARNISH	251.40	1 PC	251.40	✓
10 BOOT TOP LOCK	90.95	1 PC	90.95	X
11 BOOT LID	656.95	1 PC	656.95	✓
12 BOOT LID WEATHERSTRIP	165.62	1 PC	165.62	508.00 828.00
13 EXHAUST MUFFLER	538.10	1 PC	538.10	X
14 REAR BODY PANEL	503.30	1 PC	503.30	X
15 REAR BODY PANEL TOP GARNISH	200.76	1 PC	200.76	✓
16 REAR BUMPER	529.50	1 PC	529.50	✓
17 REAR BUMPER CLIPS	6.00	1 SET	6.00	✓
18 REAR BUMPER REFLECTOR - LH	162.50	1 PC	162.50	✓
19 REAR BUMPER REFLECTOR - RH	162.50	1 PC	162.50	✓
20 REAR BUMPER SIDE RETAINER - LH	78.05	1 PC	78.05	X
21 REAR BUMPER SIDE RETAINER - RH	78.05	1 PC	78.05	✓
22 REAR FENDER INNER TRIM - LH	369.50	1 PC	369.50	X
23 REAR FENDER INNER TRIM - RH	369.50	1 PC	369.50	X
24 REAR NUMBER PLATE LAMP - LH	103.90	1 PC	103.90	X
25 REAR NUMBER PLATE LAMP - RH	103.90	1 PC	103.90	X
26 REAR TOOL BOX	138.00	1 PC	138.00	✓
27 REAR WHEEL PANEL COVER	299.50	1 PC	299.50	✓
28 SPARE WHEEL PANEL	497.62	1 PC	497.62	X
29 TAIL LAMP LH	297.60	1 PC	297.60	X
30 TAIL LAMP RH	297.60	1 PC	297.60	✓
31 TAIL LAMP PANEL - LH	138.00	1 PC	138.00	X
32 TAIL LAMP PANEL - RH	138.00	1 PC	138.00	X
33 REAR BODY GARNISH CLIP	10.00	1 SET	10.00	X
34 REAR SPARE TYRE PANEL SPONGE - LH	155.90	1 PC	155.90	X
35 REAR SPARE TYRE PANEL SPONGE - RH	155.90	1 PC	155.90	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 02/03/2022
TP Veh Reg No: GBD6734G

Estimate No: ES2100142
Date: 07 Mar 2022
Policy No:
Veh Reg No: SJY6020C
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305169795
Engine No: 1NZY106637
Reg. Date: 17/09/2010

Estimate Repair Cost to Vehicle No :SJY6020C

Description	U/Price	Quantity	List Price	Amount
			SS	SS
36 REAR SPARE TYRE PANEL SPONGE - CENTRE	288.00	1 PC	<i>P</i> 288.00 <i>X</i>	
			7,402.20	7,402.20
Labour				
37 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,500.00	1 JOB	1,500.00	<i>600</i>
38 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	<i>700</i>
39 TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	<i>60</i>
40 TO REMOVE/RENEW EXHAUST MUFFLER.	100.00	1 JOB	<i>rr</i> 100.00 <i>X</i>	
41 TO CHECK WIRING FUNCTIONS.	40.00	1 JOB	40.00	<i>20</i>
			3,290.00	3,290.00
Total				SS 11,042.20
Add GST @ 7%				772.95
Total Amount Payable				SS 11,815.15

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND EIGHT HUNDRED FIFTEEN AND CENTS FIFTEEN ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE