



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3553B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER BLUE-DRIVE RH	NECESSARY	26.60	26.60
1	FRONT WHEEL CAP RH	SCRATCHED	346.40	346.40
1	FRONT DOOR LOWER PROTECTOR RH	SCRATCHED	186.20	186.20
	LESS 20% DISCOUNT		-111.84	-111.84
			447.36	447.36
	<u>NETT ITEMS</u>			
1	FRT DOOR COMFORTDELGRO RH (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
	<u>LABOUR</u>			
	PANEL BEATING - FRT DOOR RH ETC.		400.00	350.00
	SPRAY PAINTING - FRT BUMPER ETC.		900.00	750.00
			1,300.00	1,100.00
	GRAND TOTAL		1,814.86	1,614.86
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,614.86

Report Ref No. NS/INC22002156/Vtce2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.