



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22002157/Ety3n2 Date: 17/03/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4873K	Veh. Inspected	SHC 7882P
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/03/22/2016	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	08/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KMHC851CVLU184314	Colour	YELLOW
	Odometer	230660 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DUNLOP	4 mm
	L/H Front Tyre	195/65 R15	DUNLOP	4 mm
	R/H Rear Tyre	195/65 R15	DUNLOP	4 mm
	L/H Rear Tyre	195/65 R15	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/03/2022	Inspection Date	08/03/2022
	Survey held at	31 CORPORATION ROAD, (S) 649806		
	Repairer	DING AUTOMOTIVE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	