

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

08/03/2022 13:09

JOB-NO: 50114004

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7882P

TRANS: AUTO

CHASSIS: KMHCB51CVLU184314

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI

ENGINE: G4LEKU389505

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,600.00	0.00	1,600.00	400 -	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30 -	Y	_____
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	350.00	0.00	350.00	30 -	Y	_____
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	300.00	0.00	300.00	X	Y	_____
5 TO READJUST AND REALIGN HEADLAMP AIM	1.00	150.00	0.00	150.00	30 -	Y	_____
6 TO VACUUM AND TOPUP A/C GAS FOR A/C CONDENSER	1.00	180.00	0.00	180.00	X	Y	_____
7 TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR	1.00	300.00	0.00	300.00	X	Y	_____
8 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	200 -	Y	_____
9 TO RESPRAY FRONT BUMPER CENTER UPPER MOULDING	1.00	250.00	0.00	250.00	X	Y	_____
10 TO RESPRAY FRONT BUMPER MOULDING	1.00	250.00	0.00	250.00	X	Y	_____
11 TO RESPRAY FRONT BUMPER LOWER MOULDING	1.00	250.00	0.00	250.00	X	Y	_____
12 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00	200 -	Y	_____
TOTAL:		4,300.00	0.00	4,300.00			_____

MATERIALS

1 FRONT BUMPER COVER	1.00	430.90	86.18	344.72	L	Y	_____
2 FRONT RH BUMPER RETAINER	1.00	28.00	5.60	22.40	L	Y	_____
3 FRONT RH BUMPER SIDE SUPPORT BRACKET	1.00	12.00	2.40	9.60	L	Y	_____
4 FRONT BUMPER ENERGY ABSORBER	1.00	86.90	17.38	69.52	L	Y	_____
5 FRONT RH BUMPER MOULDING	1.00	93.00	18.60	74.40	L	Y	_____
6 FRONT RH FOG LAMP	1.00	642.50	128.50	514.00	L	Y	_____
7 FRONT RH BUMPER AIR CURTAIN DUCT	1.00	56.50	11.30	45.20	L	Y	_____
8 WIPER RESERVOIR	1.00	150.80	30.16	120.64	L	Y	_____
9 FRONT BUMPER REINFORCEMENT	1.00	1,075.10	215.02	860.08	L	Y	_____
10 FRONT BUMPER UPPER CENTER MOULDING	1.00	284.90	56.98	227.92	L	Y	_____
11 FRONT BUMPER UNDERTRAY COVER	1.00	469.40	93.88	375.52	L	Y	_____
12 FRONT RH HEADLAMP	1.00	2,110.30	422.06	1,688.24	L	Y	_____
13 FRONT RH HEADLAMP COMPUTER	1.00	841.80	168.36	673.44	L	Y	_____

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
14 FRONT RH FENDER PANEL <i>DN</i>	1.00	588.80	117.76	471.04	L	Y	3271.30
15 FRONT RH FENDER LINER <i>TH</i>	1.00	114.70	22.94	91.76	L	Y	-20%
16 FRONT RH FENDER EMBLEM <i>MC</i>	1.00	26.60	5.32	21.28	L	Y	2617.04
17 FRONT RH FENDER AND BUMPER MOUNTING BRACKET <i>X nn</i>	1.00	39.30	7.66	31.44	L	Y	
18 FRONT END MODULE CARRIER <i>X nn</i>	1.00	949.30	189.86	759.44	L	Y	
19 FRONT BUMPER CLIP SET <i>MC</i>	1.00	75.00	0.00	75.00	<i>25 S</i>	Y	
20 FRONT BUMPER RIVET SET <i>MC</i>	1.00	65.00	0.00	65.00	<i>10 S</i>	Y	
21 FRONT BUMPER UNDERTRAY COVER CLIP <i>X nn</i>	1.00	60.00	0.00	60.00	<i>S</i>	Y	
22 FRONT FENDER LINER CLIP SET <i>MC</i>	1.00	65.00	0.00	65.00	<i>20 S</i>	Y	55
23 FRONT BUMPER MOULDING CLIP <i>X nn</i>	1.00	55.00	0.00	55.00	<i>S</i>	Y	
24 RADIATOR COOLANT 4L <i>X nn</i>	1.00	130.00	0.00	130.00	<i>S</i>	Y	
TOTAL:		8,450.80	1,600.16	6,850.64			

TOTAL PARTS & LABOUR :

12,750.80 1,600.16 11,150.64

EXCESS/LOADING: S\$ 0.00

No. Of Day: 3

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: Steve (LKK)

SURVEYED BY: PIP, My Be Sy

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: