



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KOH JANICE			Ref: CS/ASM22002160/Uvy3m4 Date: 05/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 4204L	Veh. Inspected	SKQ 7863K
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M03UUU	Excess (\$)	0.00
	Assign From	KOH JANICE	Assign Date	08/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	MR053REH104518937	Colour	GREY
	Odometer	152375 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
	L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/03/2022	Inspection Date	22/03/2022
	Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	