

ASS. REG. BY:

REF:

AIG/ 22002162/Ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/vs

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SND 8812 J

Yr Regn:

11, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Telsa

(A)

Model 3

c.c

Colour

np. white

A/C:

Insured / Std / NI / NA

Sp. Reading

3282

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LRW3F7EL4MC 282975

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/35 R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

2/3/22

D.O.I.

8/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/6 @ 3098.16 Cahr 12/8/22

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

Date: 07/03/2022
Vehicle No: SND8812J
Model: TESLA MODEL 3
Chassis: LRW3F7EL4MC282975
Reg. Year: 2022

*Not Authorised
Resurvey B&P only
6 days
3096.16*

Third Party Insurer: AIG
Third Party Veh No: SFM9966P
Date of Accident: 02/03/2022
Estimator: Victor
Surveyor: Kenneth

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		Bu \$663.55
2	REAR BUMPER SIDE BRACKET RH	1		D.I \$7.48
3	REAR BOOTLID LAMP LH	1		mycom \$177.57
4	REAR BUMPER UNDER COVER	1		su \$205.61
5	REAR BUMPER REFLECTOR LH	1		su \$20.56
6	REAR BUMPER PARKING SENSOR	2	\$158.88	\$317.76
7	REAR BUMPER PARKING SENSOR BRACKET	2	\$4.67	su \$9.34
8	REAR TAIL LAMP LH	1		mycom \$280.37
9	REAR TAIL LAMP BRACKET LH	1		su \$2.80
10	REAR TAIL LAMP REFELCTOR LH	1		su \$36.45
11	REAR FENDER LH	1	R	R \$1,242.99
12	REAR FENDER INNER SHIELD LH	1		D.I \$116.82
13	REAR FENDER INNER PANEL LH	1		R \$112.15
	Rear air-dry 14.95 Rd			
	Rear reflector motor 252.34 mycom			
			SUB TOTAL	\$3,193.45
			LESS 10%	-\$319.35
			PARTS TOTAL	\$2,874.11

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		McC \$60.00
2	REAR END PANEL JOINT SEALANT	1		nn \$80.00
3	REAR FENDER QUARTER GLASS SEALANT RH	1		McC \$60.00
4	REAR FENDER INNER SHIELD CLIPS RH	1		McC \$40.00
			S/N TOTAL	\$240.00

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREA.

\$1,200.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.

\$1,000.00

LABOUR CHARGES TO REMOVE & REPLACE REAR PARKING SENSOR.

\$120.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 07/03/2022
Vehicle No: SND8812J
Model: TESLA MODEL 3
Chassis: LRW3F7EL4MC282975
Reg.Year: 2022

Third Party Insurer: AIG
Third Party Veh No: SFM9966P
Date of Accident: 02/03/2022
Estimator: Victor
Surveyor: Kenneth

LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC.

nn \$150.00 X

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

nn \$200.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 2cl

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00 3cl

LABOUR TOTAL \$2,940.00

TOTAL \$6,054.11

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

