

Date: 07/03/2022

Vehicle No: SND8812J

Model: TESLA MODEL 3

Chassis: LRW3F7EL4MC282975

Reg.Year: 2022

Third Party Insurer: AIG

Third Party Veh No: SFM9966P

Date of Accident: 02/03/2022

Estimator: Victor

Surveyor: Kenneth

*Not Withhold
Returning B&P
6 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>Bu</i> \$663.55
2	REAR BUMPER SIDE BRACKET RH	1		<i>D.I</i> \$7.48
3	REAR BOOTLID LAMP LH	1		\$177.57
4	REAR BUMPER UNDER COVER	1		<i>Sm</i> \$205.61
5	REAR BUMPER REFLECTOR LH	1		\$20.56
6	REAR BUMPER PARKING SENSOR	<i>Short 1miv</i> 2	\$158.88	\$317.76
7	REAR BUMPER PARKING SENSOR BRACKET	2	\$4.67	<i>m</i> \$9.34
8	REAR TAIL LAMP LH	1		\$280.37
9	REAR TAIL LAMP BRACKET LH	1		\$2.80
10	REAR TAIL LAMP REFELCTOR LH	1		\$36.45
11	REAR FENDER LH	1		<i>B</i> \$1,242.99
12	REAR FENDER INNER SHIELD LH	1		<i>D.I</i> \$116.82
13	REAR FENDER INNER PANEL LH	1		\$112.15
			SUB TOTAL	\$3,193.45
			LESS 10%	-\$319.35
			PARTS TOTAL	\$2,874.11

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>Mc</i> \$60.00
2	REAR END PANEL JOINT SEALANT	1		<i>nn</i> \$80.00
3	REAR FENDER QUARTER GLASS SEALANT RH	1		<i>Mc</i> \$60.00
4	REAR FENDER INNER SHIELD CLIPS RH	1		<i>Mc</i> \$40.00
			S/N TOTAL	\$240.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREA.

\$1,200.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.

\$1,000.00

LABOUR CHARGES TO REMOVE & REPLACE REAR PARKING SENSOR.

\$120.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 07/03/2022
Vehicle No: SND8812J
Model: TESLA MODEL 3
Chassis: LRW3F7EL4MC282975
Reg.Year: 2022

Third Party Insurer: AIG
Third Party Veh No: SFM9966P
Date of Accident: 02/03/2022
Estimator: Victor
Surveyor: Kenneth

LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC.

\$150.00 *601*

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$200.00 *7*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 *201*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00 *301*

LABOUR TOTAL \$2,940.00

TOTAL \$6,054.11

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

