



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLB9862S TOYOTA COROLLA ALTIS 1.6

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace rear damaged parts.	\$ 700.00 <i>200</i>
2	To putty and spray painting rear portion.	\$ 800.00 <i>200</i>
3	To apply anti rust proofing to rear left affected area	\$ 120.00 <i>x</i>
4	To check wiring and focus rear headlamp.	\$ 50.00 <i>x</i>
5	To remove and install rear undercarriage parts ^{reverse sensor}	\$ 250.00 <i>50 450</i>
6	To balance front right wheel. <i>3mm</i>	\$ 60.00 <i>x</i>
7	To conduct wheel alignment.	\$ 120.00 <i>x</i>
8	To remove and install rear exhaust system <i>rpm</i>	\$ 300.00 <i>x</i>
Total labour :		\$ 2,400.00

Total Parts: \$ 5,568.00

Total Labour \$ 2,300.00

Sub-Total \$ 7,868.00

Adrian Lij
W/S 30/03/22.
02 Days.
96893735.

Adrian Lij

total: 956.85
W/S: 750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: