

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
 BIS Automobiles Pte Ltd
 Co Reg No 201908617D, GST Reg No 201908617D



ESTIMATES

Estimate No. : 21998872
 Date Estimated : 10/03/2022
 Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
 Mr. Lee Wee Chye

- ACCOUNT -
 China Taiping Insurance (S) Pte
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909
 Motor Claims Department

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	DESCRIPTION	ORIGINAL PRICE	NETT
SMR7228R	5P19608	27/12/2019	X1	To replace front bumper and attachments, front LH chassis, front LH wheelhousing and attachments, front air duct, front support panel, bonnet, front LH/RH fenders, front LH door, rear bumper and attachments, rear LH door, rear LH fender, rear LH chassis, rear LH wheelhousing and attachments, tail end panel, trunk floor plate, boot lid include pulling and straightening on accident areas. To make good the front RH chassis, rear LH chassis and knocking out dents caused by the accident	720	18,720.00 18,000
				To spray paint front bumper, front LH/RH chassis, front LH wheelhousing, bonnet, front LH/RH fenders, front LH door, rear bumper, rear LH door, rear LH fender, rear LH/RH chassis, rear LH wheelhousing, tail end panel, trunk floor plate, LH rocker panel, LH roof frame, LH 'C' pillar and boot lid		12,650.00 10,129
				To dispatch vehicle with new engine to LTA for inspection include returning to BIS workshop		? 190.00 X
				LTA inspection fees		? 82.39 X
				To supply Front and Rear Emboss number plate		? 140.00 /
				To remove and install engine and transmission assembly to facilitate the jacking of chassis to mount car on Celette bench include conducting checks for proper function	phh	1,440.00 1152
				To replace auto transmission heat exchanger include topping up of transmission fluid, performing vehicle tests and conducting checks for leak and proper function	phh	720.00 576
				To use an engine crane to remove and install whole engine block for inspection and replacement of damaged parts affiliated to the engine including the adjustment of the engine timing in accordance with BMW specifications	phh	7,200.00 5760

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
 BIS Automobils Pte Ltd
 Co. Reg No 201906617D GST Reg No 201906617D



ESTIMATES

To replace engine mountings including re-alignment of engine block to body frame	<i>phr</i>	450.00	<i>360</i>
To replace gearbox mountings including re-alignment of gearbox to cross member and propellor shaft system		450.00	<i>360</i>
To replace engine oil cooler system including topping up engine oil and conducting checks for leak and proper function		450.00	<i>360</i>
To replace engine oil heat exchanger including topping up engine oil and conducting checks for leak and proper function		450.00	<i>360</i>
To replace charge air cooler including include conducting checks for leak and proper function		450.00	<i>360</i>
To replace radiator assembly including pressure tests, bleeding cooling system and conducting checks for leak and proper function		900.00	<i>720</i>
To replace catalyst converter include alignment and conducting checks for leaks and harmful pollutants		450.00	<i>360</i>
To replace rear exhaust silencer include alignment and conducting checks for leak and proper function		450.00	<i>360</i>
To replace center exhaust silencer include alignment and conducting checks for leak and proper function		450.00	<i>360</i>
To remove and install Front suspension, front axle and control systems to facilitate the jacking of chassis to mount car on Celette bench include replacement of damaged parts and conducting checks for proper function	<i>phr</i> <i>2040</i>	2,250.00	<i>2040</i>
To conduct checks on steering geometry including wheel alignment in accordance with BMW specifications		450.00	<i>360</i>
To replace electromechanical power steering include programming, initializing the steering column adjustment and conducting checks for proper function	<i>phr</i>	900.00	720 <i>?</i> <i>x</i>
To remove and install Rear suspension, rear axle and control system to facilitate repairs on Celette bench include the replacement of damaged parts and conducting checks for proper function	<i>phr</i>	2,250.00	<i>2040</i>
To remove and install hydraulic unit for DSC to facilitate repairs include programming and conducting checks for proper function		450.00	<i>360</i>
To remove and install Front and Rear brake discs, brake pads, brake hoses and brake calipers to facilitate repairs include bleeding of brake system, conducting brake tests and checks for leak	<i>phr</i> <i>720</i>	900.00	<i>?</i> <i>x</i>
To mount vehicle body shell frame on Celette bench to facilitate the re-alignment of body/chassis in accordance with BMW specifications	<i>phr</i> <i>2088</i>	2,610.00	<i>?</i> <i>2088</i> <i>✓</i>

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
 BIS Automobiles Pte Ltd
 Co Reg No 201906617D GST Reg No 201906617D



ESTIMATES

To conduct chassis measurements using Car-O-Tronic measuring system in accordance with BMW specifications	360	450.00	?	360 ✓
To replace Front windscreen glass include conducting rain sensor tests and water leak tests		720.00	576	
To replace rear windscreen glass include conducting heater tests and water leak tests		720.00	576	
To replace windscreen washing fluid tank and pump assembly including conducting checks for proper function		450.00	360	
To supply and install IU bracket include conducting checks for proper function		30.00	/	
To install 3M vehicle windscreen solar film (x2)		1,060.00	848	
To install 3M Rear LH vehicle quarter glass solar film		280.00	/	
To vacuum and clean car interior in order to retrieve all the possible shattered glass debris and shards caused by the accident		180.00	/	
To remove and install Rear hat-tray, rear seats, carpet and roof top lining to facilitate repairs	photo	720.00	576	
To remove and install Rear boot compartment carpet and garnish to facilitate repairs	photo	250.00	200	
To remove and install Rear vehicle quarter glass (fixed) to facilitate repairs include conducting water leak tests		150.00	/	
To replace PDC sensor wire harness and connectors include resetting and conducting checks for proper function (x2)		700.00	576	
To replace front LH/RH high intensity headlight include functionality programming and conducting checks for proper function		900.00	720	
To replace front LH/RH fog light include adjustment of the fog light beam and conducting checks for proper function		500.00	400	
To transfer lock mechanism from old to new vehicle front LH door include conducting checks on all doors sensor and central locking system for proper function		450.00	360	
To replace boot lid lock mechanism include conducting checks on all doors sensor and central locking system for proper function		450.00	360	
To replace battery positive cable, perform high current tests include charging up of battery		450.00	360	
To replace battery include conducting close circuit current tests for proper function		150.00	120	

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd
Co Reg No. 201908617D GST Reg No 201908617D



ESTIMATES

To remove and install fuse box to facilitate Front section repairs include conducting checks for proper function	450.00	360
To remove and install fuse box to facilitate Rear section repairs include conducting checks for proper function	450.00	360
To reconnect all electrical components and wirings at the Front/Rear section include conducting checks for proper function (For cut panel)	700.00	576
To replace air con condenser and air con hoses include vacuum system, top up freon gas and conducting checks for leak and proper function	900.00	720
To carry out body cavity preservation (For cut panel) (x7) 360 X 5	3,150.00	1800
To carry out body cavity preservation (x6) 80 X 5	600.00	400
To carry out Diagnosis Tests - ABL	500.00	400
Sundries	150.00	/

DESCRIPTION	UNIT PRICE	QTY	NETT
41007431525 LH EXTERIOR WHEEL HOUSE SUPPORTING / 00	185.95	1.00	185.95
41007431527 Supporting strut wheel house int left / 00	185.95	1.00	185.95
41007427781 Spring strut LH (wheel house) / 00	421.45	1.00	421.45
41007426415 LEFT INTERIORENGINE SUPPORT ? X NN	168.50	1.00	168.50
41007427299 Side panel, front left / 00 (FAL)	667.35	1.00	667.35
41007427127 Cross brace, side panel left / 00	67.20	1.00	67.20
41007427129 Extension, wheel house strut left / 00	170.45	1.00	170.45
41007355991 Bracket for gas spring left / 00	35.45	1.00	35.45
41007427135 Bracket, side panel column A left / 00 00	35.30	1.00	35.30
41007427131 Bracket, side panel top left / 00	35.30	1.00	35.30
41007436155 RR LH FENDER / 00	1,734.10	1.00	1,734.10
41007402515 TAIL PANEL / 00	405.75	1.00	405.75
41007402483 INTERIOR TAIL TRIM / 0A	318.80	1.00	318.80
41007437865 REAR LH SIDE PANEL EXTENSION / 00	72.45	1.00	72.45
83190301421 BLIND RIVET AVIBVLB / nec	0.55	70.00	38.50
83192157298 (DG/SL) BODY ADHESIVE K5B (195ML) / nec	336.75	2.00	673.50
83192158654 (DG) BODYWORK ADHESIVE K5A (50ML) / nec	116.15	2.00	232.30
7147206525 BLIND RIVET NUT WITH COLLAR M5 / nec	5.55	1.00	5.55
83120390086 CAVITY PROTECTION WAX REMOVER 500ML / nec	18.45	1.00	18.45
7147350925 COLLAR SCREW / nec	3.65	1.00	3.65
51161943122 PLASTIC NUT / nec	0.85	5.00	4.25
7147169847 PLASTIC NUT FOR COARSE THREADED PIN / nec	0.85	10.00	8.50
83192457307 PUNCH RIVET N4 / nec	0.55	70.00	38.50
83190301639 SCREW (SF PLUS M5X15) / nec	0.55	15.00	8.25
41217407919 LH REINFORCEMENT PLATE C PILLAR / 00 nec	53.75	1.00	53.75
41217407917 LH REINFORCEMENT PLATE SILL / nec	55.05	1.00	55.05
41217407921 LH REINFORCEMENT PLATE D PILLAR / nec	65.35	1.00	65.35

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co Reg No 201908017D GST Reg No 201908017D



ESTIMATES

41217275563	REINFORCEMENT PLATE UNIVERSAL / nec	52.50	1.00	52.50
41318412638	T WELD BOLT L=5.4MM / nk	0.90	10.00	9.00
41007438651	LH TRUNK FLOOR / CRU	111.90	1.00	111.90
41007463772	BONNET / 00	1,727.55	1.00	1,727.55
41007427125	BONNET LH HINGE / BT	93.20	1.00	93.20
41007427126	BONNET RH HINGE / BT	93.20	1.00	93.20
51237329410	BONNET GAS FILLED STRUT / BT	131.55	2.00	263.10
51237162448	STOP BUFFER / nec	12.00	2.00	24.00
51237435104	CONSOLE STRIKER / BT	56.00	2.00	112.00
51237431369	LH LOCK F HOOD / BT	93.30	1.00	93.30
51237431370	RH LOCK F HOOD / BT	93.30	1.00	93.30
51237495843	REAR BOWDEN CABLE ENGINE COMP. LID / TN	36.15	1.00	36.15
51767329384	FRT ENGINE HOOD SEALING / nec	60.05	1.00	60.05
51767329401	LH LOCATOR SEAL / BR	36.60	1.00	36.60
51767329402	RH LOCATOR SEAL ? X NN	36.60	1.00	36.60
51767329399	SEAL SIDE PANEL TOP LH / BR	40.05	1.00	40.05
41007414369	FRT LH DOOR / 00	1,209.80	1.00	1,209.80
41007350826	BOOTLID / 00	1,279.75	1.00	1,279.75
51767474449	BOOTLID SEALING / nec	167.30	1.00	167.30
51247463163	BOOT LID/TAILGATE PUSH BOTTON ICAM / BR	41.75	1.00	41.75
51247357112	LOCK TRUNK LID / BT	230.30	1.00	230.30
51247211294	STRIKER BOOT LID / BT	60.10	1.00	60.10
51317350597	GREEN WINDSCREEN RAIN SENSOR / BR	1,312.70	1.00	1,312.70
51317350589	COVER WINDSHIELD TOP / nec	39.85	1.00	39.85
51317350609	LH DRIP MOULDING / cat	77.30	1.00	77.30
51457055907	(S/L) SOUND INSULATION F APRON L136 / nec	73.70	1.00	73.70
61359873610	SENSOR RAIN/LIGHT/SOLAR/MISTING HUD / nec	381.60	1.00	381.60
61359856157	(S/L) REPL. SILICON PAD FOR RAIN SENSOR / nec	44.00	1.00	44.00
83192289285	(DG/SL) W/SCREEN SEALANT / nec	131.55	4.00	526.20
83199407777	(DG/SL)ADHESIVE PRIMER VP 206 (30ML) / nec	27.85	2.00	55.70
83192211217	(DG) CLEANER R1 (100ML) / nec	26.15	2.00	52.30
51317288462	BUMP STOP / nec	3.25	20.00	65.00
51377164933	HOOK AND LOOP FASTENER / nc	2.50	8.00	20.00
51317466417	REAR WINDOW (ESG) / BR	803.50	1.00	803.50
51767349643	FRT LH DOOR JOINT SEAL / nec	62.15	1.00	62.15
51767439317	FRT LH DOOR JOINT SEALING ENTRANCE / nec	36.60	1.00	36.60
51117342439	FRT BUMPER TOP CARRIER / 00	390.50	1.00	390.50
51117406385	FRT LH TOP DEFORMATION ELEMENT / 00	105.15	1.00	105.15
51117406386	FRT RH TOP DEFORMATION ELEMENT ? X NN	105.15	1.00	105.15
51118075907	IMPACT ABSORBER TOP (M ECE) / BR	287.60	1.00	287.60
51118058977	FRT BUMPER BOTTOM CARRIER (M) / BR	152.00	1.00	152.00
51117301605	FRT CROSSLINK / BR	113.15	1.00	113.15
51117302521	FRT LH BOTTOM DEFORMATION ELEMENT / BR	90.20	1.00	90.20
51117302522	FRT RH BOTTOM DEFORMATION ELEMENT / BR	90.20	1.00	90.20
51117301603	LH ADAPTER BOTTOM / BT	85.45	1.00	85.45
51117301604	RH ADAPTER BOTTOM ? X NN	85.45	1.00	85.45
51117301585	LH VERTIAL STRUT / mis	48.75	1.00	48.75
51117498085	RH VERTIAL STRUT ? X NN	48.75	1.00	48.75
51117954239	LH CLOSED GRID (BASIS/X LINE) / BR	95.55	1.00	95.55
51748493437	LH ADAPTER AIR DUCT (PDC BASIS/X) / BR	46.50	1.00	46.50
51115A2D4E1	LH TAKE UP GRILLE TRIM (PDC BASIS/X) / BR	95.55	1.00	95.55
51117954257	LH SIDE GRILLE TRIM (X LINE) / BR	87.60	1.00	87.60
51117954220	GRID CENTRE OPEN (BASIS/X LINE) / BR	111.40	1.00	111.40

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
 BIS Automobiles Pte Ltd
 Co. Reg. No. 201908617D. GST Reg. No. 201908617D



ESTIMATES

51117954213	TRIM PANEL AIRDUCT (X LINE) / cut	209.40	1.00	209.40
51748493410	AIR DUCT / BR	271.95	1.00	271.95
51748493432	LH AIR DUCT DISPLACED RADIATOR / BR	65.10	1.00	65.10
51747325044	LH HOLDER SUPPLEMENTARY COOLER BOTTOM LEF / BR	88.40	1.00	88.40
51119883249	FRT BUMPER TRIM PANEL (PDC/PMMA) / BR	871.90	1.00	871.90
51115A0B080	FRT BUMPER PANEL LOWER SECTION (PDC) / BR	218.00	1.00	218.00
51117954215	LH FOG LAMP BRACKET / BT	155.00	1.00	155.00
51117354767	FRT LH TOP MOUNTING SIDE PANEL / mis	37.00	1.00	37.00
51117354769	FRT BUMPER LH INSERT / mis	28.30	1.00	28.30
51777332337	FRT LH WHEEL ARCH TRIM / BR	161.00	1.00	161.00
51777332339	REAR LH WHEEL ARCH TRIM / BR	161.00	1.00	161.00
51127332320	RR BUMPER CARRIER / DD	516.00	1.00	516.00
51127403391	REAR BUMPER PANEL PRIMED / BR	894.35	1.00	894.35
51127403392	REAR BUMPER MIDDLE TRIM PANEL (PDC) / BR	262.95	1.00	262.95
51125A06952	REAR BUMPER TRIM PANEL (X LINE) / BR	223.60	1.00	223.60
51127379982	REAR TRIM UNDERRIDE PROTECTION (X LINE) / BR	148.90	1.00	148.90
51127332317	REAR LH BUMPER MOUNT / BR	164.35	1.00	164.35
51127332318	REAR RH BUMPER MOUNT ? X NN	164.35	1.00	164.35
51127381119	RR BUMPER LH CORNER MOUNTING / BR	145.20	1.00	145.20
51127381120	RR BUMPER RH CORNER MOUNTING ? X NN	145.20	1.00	145.20
51127378532	MOUNTING SMART OPENER / mis	46.35	1.00	46.35
51777171004	EXPANDING RIVET BLACK / nec	1.40	60.00	84.00
51138493451	FRONT GRILL (X LINE) / BR	329.10	1.00	329.10
51147376339	BMW PLAQUE WITH ADHESIVE FILM / nec	72.85	2.00	145.70
51148497376	LETTERING X1 / nec	65.60	1.00	65.60
51148496005	LETTERING S DRIVE 18i / nec	98.35	1.00	98.35
51467378621	REAR WINDOW SHELF (SCHWARZ) / BR	471.15	1.00	471.15
51477425347	LH TRUNK TRIM / CRU	142.75	1.00	142.75
51477425353	TRUNK FLOOR ? ✓ DD	570.80	1.00	570.80
51477413689	LOADING SILL COVER ? X NN	191.10	1.00	191.10
51477425349	STORAGE TROUG. LUGGAGE TRUNK FLOOR ? ✓ CRU	237.85	1.00	237.85
51467382853	LH TRIM C/D PILLAR (GRAU) / CRU	214.85	1.00	214.85
51497350851	LOWER TAIL LID TRIM PANEL (SCHWARZ) / CRU	165.50	1.00	165.50
51497407221	LH TRUNK LID PANEL TRIM (EVERESTGRAU) / cut	31.65	1.00	31.65
51497407222	RH TRUNK LID PANEL TRIM (EVERESTGRAU) / cut	31.65	1.00	31.65
51487290772	HEAT INSULATION BUMPER REAR / DD	77.30	1.00	77.30
51487290784	RR SILENCER HEAT INSULATOR / DD	77.30	1.00	77.30
51717356451	FRT LH WHEEL ARCH COVER / CRU	143.95	1.00	143.95
51717346041	REAR LH WHEEL HOUSING COVER / CRU	143.95	1.00	143.95
51647434544	CROSSLINK FRONT / DD	127.60	1.00	127.60
51647347596	SEAL COOLER TOP / nec	32.35	1.00	32.35
51647434549	FRONT PANEL V STRUT / BT	124.90	1.00	124.90
51649498329	LH SUPPORT / DD	134.30	1.00	134.30
51649498330	RH SUPPORT ? X NN	134.30	1.00	134.30
51649463153	LH HEADLIGHT MOUNTING / BR	99.55	1.00	99.55
51757343142	UNDERBONNET SCREEN ? X NN	189.10	1.00	189.10
51487471230	BONNET SOUND INSULATING / CRU	210.30	1.00	210.30
41007402407	REAR LH SIDE MEMBER ? X Repair	969.00	1.00	969.00
41117434918	RH CLOSING PLATE LONGITUDINAL MEMBER LEFT ? X NN	71.30	1.00	71.30
41117402665	LH BUMPER MOUNT ? X NN	90.65	1.00	90.65
41117402666	RH BUMPER MOUNT ? X NN	90.65	1.00	90.65
41007402459	TRUNK FLOOR ? X NN	445.65	1.00	445.65
83422409985	(S/L) SEAM SEAL 300ML ?	33.80	4.00	135.20

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
 BIS Automobiles Pte Ltd
 Co. Reg No. 201908617D. GST Reg. No. 201908617D



ESTIMATES

41007461351	RR LH DOOR X NN	1,209.80	1.00	1,209.80
51627360536	AEROBLADE (SCHWARZ) - CUT	375.30	1.00	375.30
61338492760	HORN LOW PITCH ? X NN	85.35	1.00	85.35
61627356223	REAR WIPER BLADE - CM	45.95	1.00	45.95
61627356224	REAR WINDOW WIPER ARM - CM	74.45	1.00	74.45
61627366061	WIPER ARM COVER - CM	13.65	1.00	13.65
61627356220	REAR WINDOW WIPER MOTOR ? X NN	437.20	1.00	437.20
61358494948	SENSOR LEAD SMART OPENER TOP - BR	51.20	1.00	51.20
61358494949	SENSOR LEAD SMART OPENER BOTTOM - BR	51.20	1.00	51.20
61355A044A1	CONTROL UNIT SMART OPENER ? X	504.10	1.00	504.10
13718655834	INTAKE SILENCER ? X NN	455.45	1.00	455.45
13717645645	AIR INTAKE DUCT ? X NN	177.85	1.00	177.85
11618511338	CHARGE AIR LINE ? X NN	387.20	1.00	387.20
17117634565	EXTERNAL RADIATOR ? X NN	519.45	1.00	519.45
17119894814	ROCK GUARD ? X NN	34.25	1.00	34.25
17127617374	HOSE RADIATOR ? X NN	84.95	1.00	84.95
17127617375	HOSE RADIATOR ? X NN	84.95	1.00	84.95
17118645782	RADIATOR ? ✓ DD	865.70	1.00	865.70
17517617597	CHARGE AIR COOLER ? ✓ DD	583.80	1.00	583.80
17118600126	Gasket set ? ✓ NEC	49.45	1.00	49.45
17117617617	TOP COOLING MODULE MOUNTING ? X NN	9.55	2.00	19.10
17118605551	CENTERING PIN (M6x13.6) ? X NN	5.70	2.00	11.40
17428645860	FAN HOUSING WITH FAN 600W ? ✓ BR	1,415.25	1.00	1,415.25
17118600126	Gasket set ? X NN	49.45	1.00	49.45
17138687503	EXPANSION TANK ? X NN	192.00	1.00	192.00
17117639024	COVER LID ? X NN	32.75	1.00	32.75
17128658480	HOSE RADIATOR ENGINE ? X NN	122.10	1.00	122.10
83512355290	(S/L) ANTI FREEZE 1.5 LITRES ? ✓ NEC	20.70	4.00	82.80
18308639503	REAR SILENCER - DD ? ✓ BT	1,184.25	1.00	1,184.25
18308627212	FRONT SILENCER ? ✓ BT	1,025.85	1.00	1,025.85
18308617370	HOLDER EXHAUST SYSTEM ? ✓ NEC	29.85	2.00	59.70
18307616850	RUBBER MOUNTING ? ✓ TN	18.15	2.00	36.30
18308682297	TAILPIPE TRIM BRIGHT CHROME - CR ?	119.55	1.00	119.55
18328654543	EXCH CATALYTIC CONVERTER CLOSE TO ENGINE ? X NN	1,886.85	1.00	1,886.85
22118835572	ENGINE MOUNT ? X NN	248.35	1.00	248.35
22116885788	STABILIZER LINK ? X NN	76.05	1.00	76.05
22316853453	GEARBOX MOUNT ? X NN	215.95	1.00	215.95
31116872729	FRT AXLE SUPPORT ? X NN	1,467.20	1.00	1,467.20
31126879843	LH WISHBONE WITH RUBBER MOUNTING ? X NN	286.15	1.00	286.15
31128831646	RH WISHBONE BRACKET W/RUBBER MOUNTING ? X NN	192.00	1.00	192.00
31306886751	FRT LH SPRING STRUT ? X NN	537.95	1.00	537.95
31216876645	FRT LH CARRIER ? X NN	506.35	1.00	506.35
31206874443	WHEEL HUB WITH BEARING ? X NN	511.30	1.00	511.30
33406858534	COLLAR BOLT WITH COMPRESSION SPRING ? X NN	19.80	2.00	39.60
31336892617	FRT SUPPORT BEARING ? X NN	234.95	1.00	234.95
32105a12bd8	STEERING GEAR ELECTRIC ? X NN	5,244.75	1.00	5,244.75
32106899815	LH TIE ROD ? X NN	281.75	1.00	281.75
63119477813	LH HEADLIGHT LED TECHNOLOGY ? X NN	2,688.65	1.00	2,688.65
63119477814	RH HEADLIGHT LED TECHNOLOGY - BR ? X NN	2,688.65	1.00	2,688.65
63118494844	CONTROL UNIT FRT LIGHT ELECTRONICS ? X NN	898.35	1.00	898.35
63119477821	LH LED MODULE TURN INDICATOR/DAYTIME - BR	231.15	1.00	231.15
63217477713	REAR LH LIGHT SIDE PANEL LED - BR	446.00	1.00	446.00
63217477714	REAR RH LIGHT SIDE PANEL LED ? X NN	446.00	1.00	446.00

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
 BIS Automobiles Pte Ltd
 Co. Reg. No. 201908617D. GST Reg. No. 201908617D



ESTIMATES

63217477717	REAR LH LIGHT TAILGATE LED	BR	468.30	1.00	468.30
63217477718	REAR RH LIGHT TAILGATE LED	BR X NN	468.30	1.00	468.30
63217478289	LH GUTTER STRIP	NEC	31.60	1.00	31.60
63217478290	RH GUTTER STRIP	? X NN	31.60	1.00	31.60
63267193294	NUMBER PLATE LIGHT LED	BR	28.15	2.00	56.30
63149479079	REAR LH REAR REFLECTOR	BR	39.05	1.00	39.05
63149479080	REAR RH REAR REFLECTOR	X NN	39.05	1.00	39.05
61128709821	FRT WIRING SET PDC	? X NN	107.00	1.00	107.00
61129824715	Repair wiring set rear bumper	? X NN	300.35	1.00	300.35
64509271205	CONDENSER AIR CONDITIONING WITH DRIER	MM	1,016.85	1.00	1,016.85
71236993789	LABEL COOLANT 520+/-15G	NEC	24.65	1.00	24.65
66209274427	ULTRASONIC SENSOR BLACK	BR	251.20	4.00	1,004.80
66209274428	ULTRASONIC SENSOR BLACK	BR	251.20	4.00	1,004.80
66209283203	DECOUPLING RING PDC TORQUE CONVERTER	NEC BR	5.15	9.00	46.35
66209336908	ULTRASONIC SENSOR MINERAL GREY WB39	NEC BR	383.15	1.00	383.15
66539475687	REVERSING CAMERA (VALEO)	BR	691.05	1.00	691.05
11428649177	OIL FILTER (Build in with engine & auto trans heat exchan	? X NN	841.70	1.00	841.70
51237954202	Slot cover	? X NN	67.00	1.00	67.00
51377362243	REAR LH SIDE WINDOW FIXED (ALU)	NEC	321.10	1.00	321.10
51357349663	REAR LH DOOR JOINT SEAL	X NN	36.60	1.00	36.60
51767349646	REAR DOOR SEALING TAPE ENTRANCE	X NN	36.60	1.00	36.60
11618655825	Intake manifold	? ✓ BR	825.20	1.00	825.20

Total Labour : 70,962.39
 Total Parts : 65,637.50
 Total Labour & Parts : 136,599.89
 Deduction for Excess :
 Total Repair Costs less I 136,599.89
 GST @7%: 9,561.99
 Grand Total : 146,161.88

Steve (LKK) MM PL
 8/3/22, 3.0m 40 Lyr
 P/P
 by PL dy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: