

Bik 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541
H/P 91082728

G LIMO
Blk 633A Punggol Dr
#02-675
Singapore 821633

Vehicle No : SML 8671 T
Make/Model : Honda Freed
Year : 2018

Not Notched
11/2y @ 4650 ft
Bunny Ate Pain
5 days

Qty	Description	Unit Price	Amount
<u>Estimate Cost Of Repair</u>			
1 pc	Rear tail-gate assy 1207.90		\$1,311.70 ✓
1 pc	Rear tail-gate glass moulding		\$118.20 ✓
1 pc	Rear tail-gate emblem " H "		\$45.10 ✓
1 pc	Rear tail-gate emblem : Freed "		\$50.20 ✓
1 pc	Rear tail-gate emblem " Hybrid "		\$55.10 ✓
1 pc	Rear tail-gate outer chrome handle		\$265.10 X
1 pc	Rear tail-gate inner lock		\$285.60 X 2
1 pc	Rear tail-gate inner trim board 384.70		\$485.90 2
2 pcs	Rear tail-gate lamp	\$408.10	\$816.20 X
2 pcs	Rear tail-lamp assy	\$575.60	\$1,151.20 X
2 pcs	Rear tail-lamp panel	\$283.10	\$566.20 X
1 pc	Rear windscreen wiper motor		\$325.60 X
2 pcs	Rear fender inner trim board N/S m/c m o/s	\$485.70	\$971.40 X +
2 pcs	Rear fender air vent	\$175.10	\$350.20 X
1 pc	Rear boot rubber		\$265.70 500mm
1 pc	Rear end panel 560		\$655.30 2
1 pc	Rear end panel inner garnish 145.80		\$185.90 ✓
1 pc	Rear bumper 873.10		\$1,196.30 ✓
2 pcs	Rear bumper top retainer	\$45.10	\$90.20 X
2 pcs	Rear bumper side retainer	\$38.20	\$76.40 X
2 pcs	Rear bumper reflector	\$155.70	\$311.40 X
1 pc	Rear o/s bumper reflector garnish		\$135.80 X
1 pc	Rear bumper tow cover		\$45.70 X
1 pc	Rear boot floor panel top cover board		\$405.10 X
1 pc	Rear exhaust silencer		\$687.10 2
			\$10,852.60
		Less 20 %	\$2,170.52
		balance c/f	\$8,682.08

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

SML 8671 T

S Nett

balance b/f \$8,682.08

1 pc Rear tail-gate glass sealant
1 pc Rear reverse sensor
20 pcs Rear bumper clip
1 pc Rear no plate

\$3.00

Ac	\$40.00	✓
Pn	\$200.00	X
Ac	\$60.00	✓
Pn	\$45.00	X
	<u>\$345.00</u>	

1 pc Rear tailgate edge lining - 80.00 Ac 5012 ✓
1 pc Rear bumper lower garnish - 200.00 12/101 ✓

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 6001

To putty and spray paint

\$1,200.00 6001

Check & reconnect wiring.

\$45.00 151

To respray anti-rust proofing treatment

\$120.00 601

Remove/refit rear windscreen to facilitate repair

\$100.00 ✓

Remove/refit rear tail-gate mechanism to new door.

\$150.00 601

Remove/renew rear exhaust silencer.

\$120.00 601

Remove/refit rear boot upholstery to facilitate repair.

\$100.00 601

Total

\$12,062.08