

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 17 Jun 2022

Preliminary Advice

Insured : GBD8052C

Vehicle No

TP Vehicle : SMG4417P
No

Accident Date : 07/03/2022

Make : HONDA FIT

Assignment Date : 08/03/2022

Date of : 09/03/2022

Est. Duration of : 5
Repair

Inspection

Inspection At : C.S.ONG AUTO PTE LTD (HQ)

10, ANG MO KIO IND PARK 2A #02-16 AMK AUTO POINT
SINGAPORE 568047
SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 29,204.08

Revised Amount :S\$ 6,451.76

Check Items (Estimated) :S\$ 0.00

Total :S\$ 6,451.76

Lump Sum Repair :S\$ 5,100.00

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.