



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22002174/Evy3e2	
			Date: 15/06/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMB 1476P	Veh. Inspected	SMM 5118P	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/03/22/7020	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	08/03/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUZUKI SWIFT	c.c	998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JSAAZC13S00258393	Colour	BLACK	
Odometer	47555 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	DUNLOP	5 mm	
L/H Front Tyre	185/55 R16	DUNLOP	5 mm	
R/H Rear Tyre	185/55 R16	DUNLOP	5 mm	
L/H Rear Tyre	185/55 R16	DUNLOP	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/03/2022	Inspection Date	26/04/2022	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	