

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22002176/KTY3E2

**Date:** 24/05/2022

### REFERENCE

Insured/Claimant: CHINA OFFSHORE OIL (S)  
INTERNATIONAL PTE LTD

Policy No: DMPCSNW00111462109

Date of Loss: 06/03/2022

Nature of  
Claim: OD

Claim  
No: SNM22D201615/C01/CHNGPW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKF6194Y**

Make & Model: TOYOTA ALPHARD, 2.4 (A)

Reg. Date: 20/06/2012 (Man. Year: 2012)

Colour: Metallic Black

Engine Capacity: 2362 cc

Market Value/New Car Price: S\$24,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 2AZH883808

Chassis No: JTEGD21H208230073

Odometer: 148861 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,295.00	5,490.00	1,805.00	24.74
Miscellaneous Items	688.42	526.91	161.51	23.46
Labour	882.00	483.00	399.00	45.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,865.42</b>	<b>6,499.91</b>	<b>2,365.51</b>	<b>26.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>- Excess (S\$)</b>	0.00	500.00	-500.00	
<b>(S\$)</b>	8,865.42	2,200.00	6,665.42	75.18
<b>+ GST 7.00/7.00% (S\$)</b>	620.58	154.00	466.58	75.18
<b>Nett Amount (S\$)</b>	<b>9,486.00</b>	<b>2,354.00</b>	<b>7,132.00</b>	<b>75.18</b>

### INSPECTION

Date of Assignment: 08/03/2022

Date Inspected: 09/03/2022 Inspected At:

Goldbell Engineering Pte Ltd  
5035 Ang Mo Kio Industrial Park 2 #01-367  
Singapore 569538

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2022)
Parts:	M1-MPV	TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF6194Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts		7,295.00 F	*5,490.00 F
F=Franchise part.						
Total Parts (S\$)					7,295.00	5,490.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Total Paint Including Material	688.42	526.91
Sub Total (\$\$)			688.42	526.91

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total of Labour	New	882.00	483.00
Gross Labour Cost (\$\$)			882.00	483.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >