



Mercedes-Benz

Steve (LKK) 30/3/22, 11:30 am

WIP  
My Bel sy  
3 djs

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SFM8878S

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT  
5 MAXWELL ROAD #17-00  
TOWER BLOCK, MND COMPLEX  
SINGAPORE 069110  
62239433

Vehicle & Document Information

WIP No 55402  
Reg No/Reg Date SFM8878S / 15/03/2017  
Date In/Mileage / 0  
Chassis No WDD2050402R250731  
Engine No 27491030852978  
Make/Model MB/MB C 180 SEDAN (W205) \*AVANTGARDE / A  
Colour/Trim 021 197 Obsidian B1/ 041 115 SilkBeige/E

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WE000058	Credit	07/03/2022/ 08:38	KO	301 / Kerlyn Ong				

Z REQUEST

Customer Request

M BPNSUN  
POLICY NO/ACC DATE : 2100503662-04 // 03/03/2022  
DRIVE IN/EXCESS : 04/03/2022 // FBS5563K -  
DATE IN/DATE SURVEY:  
BY/AUTHORIZED ON :

A BPILAB  
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES  
RESPRAY REAR BUMPER & RH/ REAR FENDER

A BPILAB  
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB  
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

M REAR BUMPER	1.00	1853.52	00.00	1853.52
M REAR BUMPER LOWER TRIM	1.00	252.57	00.00	252.57
M REAR BUMPER CHROME MOULDING	1.00	288.63	00.00	288.63
M LH/ REAR BUMPER BRACKET	1.00	40.46	00.00	40.46
M RH/ REAR BUMPER BRACKET	1.00	41.25	00.00	41.25
M REAR DISTANCE SENSOR	1.00	191.59	00.00	191.59
M SPACER RING	1.00	6.97	00.00	6.97
M RH/ REAR BUMPER SIDE STABILITY	1.00	68.07	00.00	68.07
M RH/ BASIC MOUNTING FOR BUMPER	1.00	68.83	00.00	68.83
M RH/ TOP BASIC MOUNTING FOR BUMPER	1.00	39.05	00.00	39.05
M RH/ REAR LAMP COMBINATION	1.00	796.77	00.00	796.77

960 / 1920.00  
800 / 1800.00

0.10 380.00 /

120.00 /

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9115 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Confirmed & accepted by

7% GST on Net 7,867.71 7,867.71 550.74

Total Payable 8,418.45

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg