

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG122002181/UTY3N2**Date:** 22/03/2022**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SJV9793B**Insured Vehicle No :** GBF3234S

Date of Loss: 04/03/2022

Nature of Claim: TP

Claim No: CDMCG22000418

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJV9793B**

Make &amp; Model: MITSUBISHI LANCER, 1.5 MIVEC A/T ELEGANCE 2WD 4DR (A)

Engine No: 4A910126344

Reg. Date: 26/02/2010 (Man. Year: 2009)

Chassis No: JMYSRCY2AAU000375

Colour: Black

Odometer: 264525 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/60R16

Rear Tyre Size:

205/60R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,750.00	1,794.60	1,955.40	52.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	720.00	340.00	32.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,810.00</b>	<b>2,514.60</b>	<b>2,295.40</b>	<b>47.72</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	4,810.00	2,000.00	2,810.00	58.42
<b>+ GST 7.00/7.00% (S\$)</b>	336.70	140.00	196.70	58.42
<b>Nett Amount (S\$)</b>	<b>5,146.70</b>	<b>2,140.00</b>	<b>3,006.70</b>	<b>58.42</b>

**INSPECTION**

Date of Assignment: 08/03/2022

Date Inspected: 08/03/2022 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 21 Mar 2022)

**Parts:** 143 MITSUBISHI LANCER 1.5 MIVEC A/T ELEGANCE 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJV9793B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed/Torn	1,080.00 F	*1,045.00 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	66.00 F	*48.00 FL
3	1		*FRONT BUMPER FOG LAMP COVER O/S	Serviceable	84.00 F	*- FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*FRONT FENDER O/S	Repair	455.00 F	*- FL
6	1		*FRONT HEADLAMP O/S	Cracked	2,015.00 F	*851.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,750.00</b>	<b>1,994.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	199.40
<b>Total Parts (\$\$)</b>	<b>3,750.00</b>	<b>1,794.60</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	80.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	380.00	300.00
5	TO PUTTY & SPRAY PAINTING	New	500.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>1,060.00</b>	<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >