

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURA	NCE BHD	Ref:	CS3/LPC22002182/y3	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date	: 08/03/2022	
			Code	e: LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XD 4728C	Veh. Inspected	GBD 7525L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	LWP/TSM/4855/22/sm	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	08/03/2022	
2. Vehicle Particulars & Condition					
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
5.	General Information				
	Accident Date	07/03/2022	Inspection Date	09/03/2022	
	Survey held at	vey held at TIAN SIANG MOTOR 27-A JURONG PORT ROAD #01-19, JURONG INDUSTRIAL ESTATE SINGAPORE 619101			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				