



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SMU301S

Report No. : PAS/TP/0080921

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
				2012	
1	1 pc	Frt bumper	Dented/Deformed	2944.10 \$ 3,923.30	CUTV \$ 3,923.30
2	1 pc	Frt bumper park sensor RH	Dented/Damaged	✓ \$ 236.50	90V \$ 236.50
3	1 pc	Frt fender RH	Dented/Distorted	✓ \$ 1,455.70	CUTV \$ 1,455.70
4	1 pc	Frt fender cowling RH	Refit	\$ 250.30	
5	1 pc	Frt fender air vent moulding RH	Refit	\$ 138.60	NDX \$ -
6	1 pc	Frt fender signal lamp RH	Grazed/Defaced	\$ 182.40	NDX \$ 182.40
7	1 pc	Frt alloy rim RH	Dented/Defaced	\$ 1,820.30	NCX \$ 1,820.30
8	1 pc	Frt knuckle arm RH	Refit	\$ 1,329.70	NDX \$ -
9	1 pc	Frt lower arm RH	Bent	\$ 1,209.00	BT ✓ \$ 1,209.00 ND
10	1 pc	RH side mirror assy	Cracked/Damaged	\$ 1,021.20	CUT RX \$ 1,021.20
11	1 pc	Frt door RH	Dented/Repair		(Refer labour no. 4 & 5)
				\$ 11,567.00	\$ 9,848.40
Less Discount : 10%				\$ 1,156.70	10% \$ 984.84
List Parts Sub-Total :				\$ 10,410.30	\$ 8,863.56

Parts Total : \$ 10,410.30 \$ 8,863.56

4636.30
 @ 10% 463.63
 4172.67



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SMU301S

Report No. : PAS/TP/0080921

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove and reinstall affected electrical wiring system for necessary repairs. To check electrical system and calibrate/focus headlamp.	\$ 70.00	\$ 50.00 <i>NNX</i>
2	To remove, check and replace RHF undercarriage parts.	\$ 150.00	\$ 120.00 ✓
3	To conduct wheel alignment.	\$ 60.00	\$ 60.00 ✓
4	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 660.00 <i>400.00</i>
5	To spray painting, blending on affected and adjacent area.	\$ 1,000.00	\$ 850.00 <i>600.00</i>
6	To spray anti-rust coating on new and affected panels.	\$ 60.00	\$ 60.00 <i>NNX</i>
Labour Total :		\$ 2,340.00	\$ 1,800.00
Total (Parts & Labour) :		\$ 12,750.30	\$ 10,663.56
			1800.00

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 8,530.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 6 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

63 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Lump sum repair
Repair days 5

Parts 4172.67
SN -
Labour 1800.00
5352.67
@ 20% 1070.53
4282.14

LS 4300.12

Tan Min 14/3/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.