



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR21012734/Gvy3e2-1	
			Date: 28/03/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 6273Z	Veh. Inspected	FBQ 8869U	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/11/21/2060	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	08/03/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA MX KING T150	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	MH3UG0750KK043659	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	80/90-17	PIRELLI	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80-17	PIRELLI	5 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/11/2021	Inspection Date	20/12/2021	
Survey held at	464 MACPHERSON ROAD			
Repairer	MOTO 51 PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	