

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## INVOICE

To: Dr Delivery Pte Ltd  
c/o 2 Kaki Bukit Ave 2  
#01-17 Kaki Bukit Autohub  
Singapore 417921


Date : 27/12/2021

Invoice No : IV21-12020/CAS

| Particulars                                                                                                                                                                                                               | Amount   |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| Fee For Services Rendered In Respect Of:<br><br>Surveying, Adjusting, and Re-inspection Of<br>Accident Damaged Vehicle FBQ 8869U<br>(Inclusive Of Photographs And Transport Charges)<br><br>Our reference : CAS/21-12/020 | \$531.00 |
| Total                                                                                                                                                                                                                     | \$531.00 |

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## Automobile Inspection Report

|                                                                                                    |                                                                                      |                        |                              |
|----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|------------------------|------------------------------|
| To: Dr Delivery Pte Ltd<br>c/o 2 Kaki Bukit Ave 2<br>#01-17 Kaki Bukit Autohub<br>Singapore 417921 |                                                                                      | Date : 27/12/2021      | Reference No : CAS/21-12/020 |
| <b><u>General Information</u></b>                                                                  |                                                                                      |                        |                              |
| Registration No.                                                                                   | : FBQ 8869U                                                                          |                        |                              |
| Accident Date                                                                                      | : 26/11/2021                                                                         |                        |                              |
| <b><u>Particulars of Damaged Vehicle</u></b>                                                       |                                                                                      |                        |                              |
| Colour                                                                                             | : Black                                                                              | Make & Model           | : Yamaha MX King T150        |
| Engine Capacity                                                                                    | : 150 cc                                                                             | Pre-Accident Condition | : Good                       |
| Mileage (KM)                                                                                       | : 20756                                                                              | Engine No.             | : G3E6E0541690               |
| Chassis No.                                                                                        | : MH3UG0750KK043659                                                                  | Steering               | : Affected                   |
| Registration Date                                                                                  | : 02/01/2020                                                                         | Brake                  | : In Order                   |
| <b><u>Tyre Condition</u></b>                                                                       |                                                                                      |                        |                              |
|                                                                                                    | Size                                                                                 | Make                   | Balance                      |
| Front Tyre                                                                                         | 80/90R17                                                                             | PIRELLI                | 90%                          |
| Rear Tyre                                                                                          | 90/80R17                                                                             | PIRELLI                | 70%                          |
| <b><u>Inspection</u></b>                                                                           |                                                                                      |                        |                              |
| Repairer                                                                                           | : Moto 51 Pte Ltd<br>2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921 |                        |                              |
| <b><u>Adjustment And Recommendation Cost Of Repair</u></b>                                         |                                                                                      |                        |                              |
| Repairer's Estimate                                                                                | : \$3,642.40                                                                         |                        |                              |
| Revised Amount                                                                                     | : \$2,000.00                                                                         |                        |                              |
| Less Excess                                                                                        | : -                                                                                  |                        |                              |
| Nett Total                                                                                         | : \$2,000.00                                                                         |                        |                              |
| <b><u>Remarks</u></b>                                                                              |                                                                                      |                        |                              |
| (A) Survey was done on 20/12/2021                                                                  |                                                                                      |                        |                              |
| (B) Re-survey was done on 20/12/2021                                                               |                                                                                      |                        |                              |
| (C) Re-survey after repair was done on 21/12/2021                                                  |                                                                                      |                        |                              |
| (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.                                  |                                                                                      |                        |                              |
| (E) We have NOT given any instruction to authorize the repair of the vehicle.                      |                                                                                      |                        |                              |

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Constant Appraiser Services**

Vehicle No : FBQ 8869U

Our ref : CAS/21-12/020

**Adjustment On Repair Costs And Replacement Of Parts:**

| S/No                                                                | Qty  | Descriptions                                                                                                                                                                   | Assessed Condition | Estimate by Workshop (\$) | Revised Amount (\$) |
|---------------------------------------------------------------------|------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|---------------------------|---------------------|
| <u>PARTS REPLACEMENT – LIST ITEMS</u>                               |      |                                                                                                                                                                                |                    |                           |                     |
| 1                                                                   | 1pc  | Exhaust muffler                                                                                                                                                                | Repair             | 450.00                    | -                   |
| 2                                                                   | 1pc  | Exhaust muffler end cover                                                                                                                                                      | Grazed             | 61.00                     | 61.00               |
| 3                                                                   | 1pc  | Exhaust muffler protector                                                                                                                                                      | Grazed             | 133.00                    | 133.00              |
| 4                                                                   | 2pcs | Fork assy R/L @ \$355.00                                                                                                                                                       | Bent/Twisted       | 710.00                    | 710.00              |
| 5                                                                   | 1pc  | Fork under bracket                                                                                                                                                             | Repair             | 195.00                    | -                   |
| 6                                                                   | 1pc  | Front brake disc                                                                                                                                                               | Serviceable        | 195.00                    | -                   |
| 7                                                                   | 1pc  | Front fender                                                                                                                                                                   | Grazed             | 89.00                     | 89.00               |
| 8                                                                   | 2pcs | Front footrest R/L @ \$62.00                                                                                                                                                   | Serviceable        | 124.00                    | -                   |
| 9                                                                   | 1pc  | Front wheel rim                                                                                                                                                                | Dented/Warped      | 485.00                    | 485.00              |
| 10                                                                  | 1pc  | Front wheel rim shaft                                                                                                                                                          | Repair             | 55.00                     | -                   |
| 11                                                                  | 1pc  | Handle bar                                                                                                                                                                     | Grazed             | 145.00                    | 145.00              |
| 12                                                                  | 2pcs | Rear footrest bracket R/L @ \$85.00                                                                                                                                            | Repair             | 170.00                    | -                   |
| 13                                                                  | 2pcs | Rear footrest R/L @ \$62.00                                                                                                                                                    | O/S Grazed         | 124.00                    | 62.00               |
|                                                                     |      |                                                                                                                                                                                |                    | 2,936.00                  | 1,685.00            |
| Less 10%                                                            |      |                                                                                                                                                                                |                    | (293.60)                  | (168.50)            |
| Sub total                                                           |      |                                                                                                                                                                                |                    | 2,642.40                  | 1,516.50            |
| <u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>                       |      |                                                                                                                                                                                |                    |                           |                     |
| 1                                                                   | 2pcs | Fork oil seal R/L @ \$25.00                                                                                                                                                    | Necessary          | 50.00                     | 50.00               |
| 2                                                                   | 1set | Lever set                                                                                                                                                                      | Grazed             | 120.00                    | 120.00              |
| 3                                                                   | 1set | Mirror set                                                                                                                                                                     | Grazed             | 135.00                    | 135.00              |
| 4                                                                   | 1set | Steering cone/bearing set                                                                                                                                                      | Necessary          | 165.00                    | 165.00              |
| Part total                                                          |      |                                                                                                                                                                                |                    | 3,112.40                  | 1,986.50            |
| <u>LABOUR &amp; MISC. CHARGES</u>                                   |      |                                                                                                                                                                                |                    |                           |                     |
| 1                                                                   |      | To remove, reinstall electrical wiring harness, check lighting. (to FR)                                                                                                        |                    | 80.00                     | 30.00               |
| 2                                                                   |      | To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident |                    | 450.00                    | 300.00              |
| Grand total                                                         |      |                                                                                                                                                                                |                    | 3,642.40                  | 2,316.50            |
| Recommended cost of lump sum repair (To its pre-accident condition) |      |                                                                                                                                                                                |                    |                           | 2,000.00            |

**Constant Appraiser Services**

Vehicle No : FBQ 8869U

Our ref : CAS/21-12/020


**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.


The repairer has agreed to undertake the job at a lump sum of **\$2,000.00** on a contractual basis. Under normal circumstances, the repair period would be about **2 (Two)** working days.




Yours faithfully,


**Constant Appraiser Services**




Lim Yong Tian (Sebastian)  
Licensed Appraiser  
Adv. Dip. In Mechanical Engineering (AUS)  
MSAAA
















Constant Appraiser Services









Constant Appraiser Services




---

















Constant Appraiser Services

