

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0162/2022/JT
DATE	:	7-Mar-22
WIP	:	14510

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 Attn: Motor Claims Dept
 Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MR TAN KUAN TIAN
ADDRESS	:	46 CHU LIN ROAD
	:	SINGAPORE 669940
TELEPHONE	:	HP +65 97974246
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800073006-03
VEHICLE NO	:	SMC 900 H
MODEL CODE	:	AUDI A4 SEDAN 1.0 TFSI
MODEL YEAR	:	5/7/2018
ENGINE NO	:	CVK 058920
CHASSIS NO	:	WAUZZZF41JA148372
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	3-Mar-22
PLACE OF ACCIDENT	:	JUNCTION OF LORONG MAMBONG / HOLLAND ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 900 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO REMOVE AND RENEW AIRCON CONDESER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00	?
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	Without lock carrier 1000 With lock carrier 2250
5	TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER.	\$ 3,000.00	1650
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192
TOTAL LABOUR CHARGES		: \$ 9,814.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 900 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,787.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 629.00	✗
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 79.00	✓
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 218.00	✗
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$ 254.00	✗
6	FRONT BUMPER AIR GUIDE - RH <i>new</i>	1	\$ 72.00	✓
7	RADIATOR GRILLE <i>new</i>	1	\$ 1,478.00	✗
8	RADIATOR AIR GUIDE GRILLE - RH <i>3 new</i>	1	\$ 151.00	✗
9	RADIATOR GUIDE SECTION - RH	1	\$ 41.00	✗
10	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 143.00	✗
11	CAUTION STICKER <i>3 new</i>	1	\$ 16.00	✗
12	AIR COND STICKER	1	\$ 9.00	✗
13	HORN - RH ?	1	\$ 139.00	?
14	HORN SUPPORT - RH ?	1	\$ 33.00	?
15	FRONT PARKING AID SENSOR - INNER / OUTER ?	2	\$ 488.00	?
16	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 10.00	✗
17	FRONT FENDER - RH <i>Dented</i>	1	\$ 861.00	✓
18	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 211.00	✗
19	FRONT FENDER CLOSING ELEMENT - RH <i>new</i>	1	\$ 81.00	✓
20	FRONT FENDER BRACKET - RH ?	1	\$ 41.00	✗
SUB TOTAL SPARE PARTS		:	\$ 6,741.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 900 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET CENTER - RH <i>new</i>	1	\$ 55.00	+
22	POP RIVET <i>new</i>	6	\$ 23.00	✓
23	FRONT FENDER BRACE - RH <i>Bent</i>	1	\$ 132.00	✓
24	FRONT WHEEL HOUSING LINER - RH <i>Rehd</i>	1	\$ 262.00	✓
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 219.00	+
26	FRONT WHEEL SPOILER <i>new</i>	1	\$ 82.00	+
27	FRONT WHEEL SPOILER LOWER - RH <i>new</i>	1	\$ 40.00	+
28	FRONT FENDER LEDGE COVER LONG - RH <i>?</i>	1	\$ 35.00	?
29	FRONT FENDER LEDGE COVER SHORT - RH <i>Rehd</i>	1	\$ 26.00	✓
30	HEADLIGHT - RH <i>cracked</i>	1	\$ 7,693.00	✓
31	HEADLIGHT POWER MODULE <i>?</i>	1	\$ 840.00	?
32	HEADLIGHT CONTROL UNIT <i>?</i>	1	\$ 840.00	?
33	HEADLIGHT HOSE - RH <i>new</i>	1	\$ 42.00	+
34	SPACER <i>?</i>	3	\$ 136.00	?
35	LOCK CARRIER <i>?</i>	1	\$ 1,127.00	?
36	LOCK CARRIER SUPPORT - RH <i>?</i>	1	\$ 43.00	?
37	RADIATOR COOLANT <i>?</i>	6	\$ 282.00	?
38	RADIATOR AIR GUIDE - RH OUTER <i>?</i>	1	\$ 32.00	+
39	RADIATOR AIR GUIDE - RH INNER <i>new</i>	1	\$ 14.00	+
40	RADIATOR AIR GUIDE - UPPER <i>new</i>	1	\$ 19.00	+
SUB TOTAL SPARE PARTS		:	\$ 11,942.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 900 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER - RH ?	1	\$ 231.00	?
42	LIFT CYLINDER BRACKET - RH ?	1	\$ 7.00	?
43	LIFT CYLINDER CORRUGATED PIPE men	1	\$ 107.00	+
44	FRONT NO PLATE ME	S/N	\$ 60.00	+
45	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 19,488.00	
TOTAL LABOUR CHARGES		:	\$ 9,814.00	
GRAND TOTAL		:	\$ 29,302.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Admin Lj
SURVEYED DATE : 08/08/22.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 05 days (Without lock carrier)
08 days (With lock carrier)

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT