



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
 WORKSHOP : UBI ROAD 1
 CONTACT NO : 6366 2323
 FAX NO : 6841 1183
 REFERENCE : PA/OD/0164/2022/JT
 DATE : 7-Mar-22
 WIP : 14628

Xiao Chen.
10 + 4 = 14 Days.
\$26773.20.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 Attn: Motor Claims Dept
 Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR SADAT QAYYUM
 ADDRESS : 30 MOUNT ELIZABETH
 #03-30
 SINGAPORE 228519
 TELEPHONE : HP +65 93252488
 TYPE OF CLAIM : OWN DAMAGE CLAIM
 POLICY NO : 7210054291
 VEHICLE NO : **SNA 7786 Z**
 MODEL CODE : AUDI A6 2.0 TFSI S
 MODEL YEAR : 31/5/2021
 ENGINE NO : DKY 015489
 CHASSIS NO : WAUZZZF24MN071864
 MILEAGE : -
 DATE IN : -
 ESTIMATED BY : JOHNNY BOO / ALLAN WU
 ACCIDENT DATE : 4-Mar-22
 PLACE OF ACCIDENT : JUNCTION OF STAMFORD ROAD
 AND ESPLANDE DRIVE



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 7786 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE THE RENEWAL OF LHS REAR FENDER.	S/N \$ 600.00	X
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS.	S/N \$ 400.00	X
4	TO CARRY OUT WATER SEEPAGE TEST.	S/N \$ 200.00	X
5	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	560 ✓
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS. ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	X
SUB TOTAL LABOUR CHARGES		: \$ <u>3,760.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 7786 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	X
8	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, LHS B-PILLAR LOWER TRIMS. TO DISLODGE AND REINSTALL CARPET TO FACILITATE THE RENEWAL FOR LHS B-PILLAR AND LHS SILL PANEL.	S/N \$ 980.00	? ✓
9	TO DISMANTLE AND RENEW REAR BUMPER, LHS SILL PANEL TRIM, LHS REAR DOOR AND LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL AND LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4500 11,200.00	Without B Pillar 2500. With B Pillar 3500.
10	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, DOOR HANDLES, LHS WING MIRROR COVER, LHS SILL PANEL TRIM, LHS B-PILLAR, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE. REAR END PANELLING.	\$ 4600 10,000.00	7 x 550 = 3850. Handle : 100 Mirror : 100 <u>4050</u>
11	TO RENEW LHS REAR RIM AND CARRY OUT ALIGNMENT TEST	S/N \$ 280.00	✓
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 27,812.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NURA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 7786 Z - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	B-PILLAR FRAME - LH <i>Repaired Dented.</i>	1	\$ 4,506.00	3604.80 ? 3604.80 ✓
2	REAR WINDSCREEN <i>new</i>	1	\$ 1,307.00	+
3	QUARTER WINDOW STRIP - LH / RH <i>new</i>	2	\$ 7.00	+
4	QUARTER WINDOW - LH <i>new</i>	1	\$ 788.00	+
5	PRIMER <i>new</i>	2	\$ 44.00	+
6	SILL TRIM STRIP - LH REAR <i>new</i>	1	\$ 133.00	X. 106 ✓
7	SILL TRIM STRIP - LH FRONT <i>new</i>	1	\$ 209.00	+
8	B-PILLAR TRIM - LH <i>Repaired</i>	1	\$ 960.00	✓ 768
9	B-PILLAR ATTACHMENT PARTS <i>new</i>	1	\$ 136.00	✓ 108.80
10	B-PILLAR ADHESIVE TAPES <i>new</i>	1	\$ 64.00	✓ 51.12
11	REAR BUMPER <i>Repaired</i>	1	\$ 3,012.00	+
12	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 246.00	+
13	REAR BUMPER GUIDE SECTION - LH LOWER <i>new</i>	1	\$ 71.00	+
14	REAR DOOR - LH <i>Distorted</i>	1	\$ 4,489.00	✓ 3591.20
15	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 191.00	✓ 152.80
16	REAR DOOR SEAL - LH <i>Not new</i>	1	\$ 206.00	X.
17	REAR DOOR CATCH - LH <i>Not new</i>	1	TBC	? X
18	REAR DOOR HINGE - LH LOWER <i>Not new</i>	1	TBC	? X
19	REAR DOOR HANDLE - LH <i>new</i>	1	\$ 389.00	+
20	REAR DOOR HANDLE PLATE - LH <i>new</i>	1	\$ 109.00	+
21	REAR DOOR HANDLE PANEL UPPER PART CAP - LH <i>new</i>	1	\$ 100.00	+
SUB TOTAL SPARE PARTS		:	\$ 16,967.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 7786 Z - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT DOOR - LH <i>Distorted</i>	1	\$ 4,489.00 ✓	3591.20	
2	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$ 191.00 ✓	152.80	
3	FRONT DOOR CATCH - LH <i>Not nec</i>	1	TBC	? X	
4	FRONT DOOR COVER - LH <i>new</i>	1	\$ 121.00 +		
5	FRONT DOOR HANDLE - LH <i>cut</i>	1	\$ 389.00 ✓	310.80	
6	FRONT DOOR HANDLE TRIM HANDLE - LH <i>cut</i>	1	\$ 109.00 ✓	86.80	
7	FRONT DOOR PANEL UPPER PART CAP - LH <i>new</i>	1	\$ 100.00 +		
8	FRONT DOOR HANDLE SENSOR - LH <i>Not nec</i>	1	\$ 278.00 ?	X	
9	FRONT DOOR SLIDE VALVE - LH <i>Not nec</i>	1	\$ 15.00 +		
10	FRONT DOOR HANDLE UNDERLAY - LH <i>nec</i>	1	\$ 6.00 +	4.40 ✓	
11	FRONT DOOR HANDLE UNDERLAY OUTER - LH <i>nec</i>	1	\$ 7.00 +	5.36 ✓	
12	FRONT DOOR HANDLE MOUNTING BAR - LH <i>Not nec</i>	1	TBC	+	
13	WING MIRROR MOUNTING - LH <i>Not nec</i>	1	\$ 3,069.00 ?	X	
14	FRONT DOOR WINDOW REGULATOR - LH <i>Damaged</i>	1	\$ 385.00 +	308 ✓	
15	FRONT DOOR WINDOW MOTOR - LH <i>Not nec</i>	1	\$ 376.00 +		
16	FRONT DOOR WINDOW SLOT SILL TRIM STRIP - LH OUTER	1	\$ 224.00 +		
17	PICTOGRAM STICKER <i>new</i> nec	1	\$ 27.00 +	21.28 ✓	
18	FRONT ALUMINIUM RIM <i>new</i> <i>cut</i>	1	\$ 1,847.00 ✓	1477.60	
19	RUBBER VALVE <i>Not nec</i>	4	\$ 15.00 +		
20	STONE CHIP <i>Nec</i>	S/N	\$ 180.00 +	✓	
SUB TOTAL SPARE PARTS		:	\$ 11,828.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 7240 K - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	METAL FILLER POWDER <i>Nec</i>	S/N	\$ 280.00	? ✓
22	ARYLIC SEALANT <i>Nec</i>	S/N	\$ 180.00	? ✓
23	CAVITY WAX <i>Nec</i>	S/N	\$ 140.00	? ✓
24	REAR WINDSCREEN SEALANT <i>Nec</i>	S/N	\$ 200.00	✓
25	1/4 GLASS SEALANT <i>Nec</i>	S/N	\$ 100.00	✓
26	SUNDRIES <i>Nec</i>	\$	500.00	713.44 ✓
TOTAL SPARE PARTS (FRONT & REAR)		:	\$ 30,195.00	
TOTAL LABOUR CHARGES		:	\$ 27,812.00	
GRAND TOTAL		:	\$ 58,007.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian

SURVEYED DATE

: 08/03/22

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, B Pillar 10 Days
Without B Pillar 07 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT