

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/03/2022

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB319S
Case Reference Number	BUS/03/22/7001
Registration Date	16/10/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Seng Han Feng
Type of Accident	Side Swipe
Accident Date and Time	4/3/2022 6:19 AM
Accident Reported Date and Time	4/3/2022 7:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC if any	SMB319S - Front right windscreen cracked and headlight cover cracked PA9929S (TP) - INSURED WITH NTUC
Prepared Date and Time	8/3/2022 2:25 PM
Chassis Number	WMAA22Z20C7001451
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$5,931.27	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$8,867.27	\$0.00
Lump Sum Total	\$8,650.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	Kok Khoo Goh	
ARC / Surveyor Sign Off Date	08/03/2022 2:31 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/03/2022

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00	1590
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	446
Total Spray Painting & Panel Beating	\$616.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	
Total Other Costs	\$200.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010148	GLASS	4001X01-GLASS5171	WINDSCREEN, FRONT F OR MAN A22 BUS	1.00	\$5,031.80	10.00	\$4,528.62	Replace	CR
4006315	CONSUMABLE	Aktivator - 100	ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	CR
4006314			SEALANT SIKAFLEX	10.00	\$37.00	0.00	\$370.00	Replace	CR
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	CR
6000917			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	CR
6010152	Body	F01001-CW266	COVER, HEADLAMP FRT RH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	CR
6010305	VE	81.25101-6540	HEADLAMP, RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	CR
6010307	VE	81.25320-6112	FLASHER, AUX HEADLAMP, RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	CR
Total					\$8,746.50		\$8,228.05		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2036.00
7414.09

9450.09

20%

7560.07

45-7,550

RAME

Hp 800 10068

3 days

LI

08/03/22 P Mon

Reg after regit